

Active Screening Assessment Reports (ASARs) for GatherCo Sale Facilities

Phase II

July 1999

Revised February 2000

Prepared By:



West Chester, Pennsylvania

This document is being submitted to an Administrative Order on Consent issued by the U.S. Environmental Protection Agency, Docket No. III 94 35 DC. Columbia Gas Transmission Corporation does not waive any, and expressly reserves all, rights and privileges it may have with respect to this document and any documents supporting this submission.

ACTIVE SCREENING ASSESSMENT REPORTS (ASARs) FOR GATHERCO-PHASE II SALE AREA

Submitted By COLUMBIA GAS TRANSMISSION CORPORATION Charleston, West Virginia

July 1999

Revised February 2000

Prepared by

ROY F. WESTON, INC. West Chester, Pennsylvania

INTRODUCTION

This document was prepared pursuant to the Active Screening Assessment requirements of the Administrative Order on Consent for Removal Actions (AOC), between Columbia Gas Transmission Corporation (Columbia) and the U. S. Environmental Protection Agency (EPA). Two work plans were prepared and approved by EPA under Section 8.5 of the AOC, which set forth requirements for assessing liquid removal points and mercury measuring stations. Those work plans are: the Active Screening Assessment Work Plan for Gathering Line LRPs (April 1997); and the Mercury Measuring Stations Work Plan (April 1997), which also includes provisions for removal actions.

Certain segments of the Columbia pipeline system are referred to as the "Gathering System." Liquid removal points (LRPs) along this system are also known as "Production" drips (see Item 9 on Liquid Removal Point Questionnaire). This system is the portion of Columbia's pipeline system that has transported only locally produced and purchased natural gas which, as a result of its design, could not carry PCB contaminated gas. Certain of Columbia's pipelines on the Gathering System, however, were contaminated with PCBs resulting from interconnections with other pipeline companies that used PCB containing lubricants in their natural gas compressors. During the course of the Gathering Line LRP investigation, Columbia discovered that certain of the lines had two-way valves which would allow gas to flow in two directions, or to "backflow" back upstream from PCB contaminated transmission lines. As assessments were conducted under the ASA program, these sites were also sampled for PCBs. Therefore, when Item 14 on the LRP Questionnaire indicates that a site was backfed, there should be corresponding analytical data for PCBs.

Included herein are individual Active Screening Assessment Reports (ASARs) for each site where Columbia has conducted an active screening assessment and contends that no further investigation or cleanup is warranted under the AOC. Each report includes site specific data, including sampling results, photographs, and sketches, and are arranged numerically by facility identification number. The individual reports are generated automatically from the ASA database, therefore the information found in the Summary of Findings and Recommendations sections is generally redundant with usually only the facility identification number changing. The sites presented in this document are part of the GatherCo-Phase II sale area and are being transferred to a third party.

Table 1 ASAR Facilities

GatherCo-Phase II Sale Area

Facility ID	Description
L05001	SIPHON ON LINE J-46 AT STATION 1062+52
L05002	HORIZONTAL DRIP ON LINE J
L05003	HORIZONTAL DRIP ON LINE J
L05004	HORIZONTAL DRIP ON LINE J AT STATION 1114+80
L05005	HORIZONTAL DRIP ON LINE J AT STATION 1149+93
L05006	HORIZONTAL DRIP AT METER 720307 ON LINE J-54
L05007	HORIZONTAL DRIP ON LINE J-54 AT STATION 194+64
L05008	HORIZONTAL DRIP ON LINE J-54 AT STATION 297+15
L05009	DISPLACEMENT METER 731230 ON LINE Q-930WM OIL DECATUR WESTVACO
L05010	DISPLACEMENT METER 732042 ON LINE Q-926
L05011	DISPLACEMENT METER 722705 ON LINE Q-926EAGLE MTN EDDY
L05012	HORIZONTAL DRIP ON LINE Q-926 AT STATION 617+39
L05013	SIPHON ON LINE H-118 AT STATION 243+28
L05014	HORIZONTAL DRIP ON LINE J-54
L05015	DISPLACEMENT METER 717465 ON LINE Q-926FS CAMP
L05016	DISPLACEMENT METER 712382 ON LINE Q-926ANCHORAGE DYE
L05017	VERTICAL DRIP AT DM 712382 ON LINE Q-926 AT STATION 998+64
L05018	DISPLACEMENT METER 722706 ON LINE Q-926
L05019	MCTAGGART KELLY DISPLACEMENT METER 703027 ON LINE Q-926
L05020	ENERGY-REED DISPLACEMENT METER 730823 ON LINE Q-926
L05021	REEDSVILLE T.B. & R.S. DISPLACEMENT METER 710995-1 ON LINE Q-926
L05022	REEDSVILLE T.B. & R.S. DISPLACEMENT METER 710995-2 ON LINE Q-926
L05023	COOLVILLE T.B. & R.S. DISPLACEMENT METER 710700-1 ON LINE Q-926
L05024	COOLVILLE T.B. & R.S. DISPLACEMENT METER 710700-2 ON LINE Q-926
L41227	VERTICAL DRIP ON LINE LW-529 AT WELL 529
L41228	HORIZONTAL DRIP ON LINE LW-2407 AT STATION 5+20 AT WELL 2407
L41229	HORIZONTAL DRIP ON LINE L-2975 AT STATION 678+88
L41230	HORIZONTAL DRIP ON LINE L-2975 AT STATION 18+61
L41231	HORIZONTAL DRIP ON LINE L-2988 AT STATION 84+43
L41232	DISPLACEMENT METER 709933 ON LINE FK-106
L41233	VERTICAL DRIP AT DM 709933 ON LINE FK-106
L41234	SIPHON ON LINE J-54

Table 1 ASAR Facilities GatherCo-Phase II Sale Area

Facility ID	Description
L41235	HORIZONTAL DRIP ON LINE J-54
L41236	HORIZONTAL DRIP ON LINE J AT STATION 11+47
L41237	DISPLACEMENT METER 709730-1 ON LINE L-2310
L41238	DISPLACEMENT METER 709730-2 ON LINE L-2310
L41239	HORIZONTAL DRIP AT DM 709730 ON LINE L-2310 AT STATION 79+08
L41240	DISPLACEMENT METER 734663 ON LINE J
L41241	REMOVED DISPLACEMENT METER 722644 ON LINE J
L41242	VERTICAL DRIP ON LINE J AT STATION 356+73
L41243	SIPHON ON LINE J AT STATION 356+73
L41244	SIPHON ON LINE J AT STATION 342+90

Table 2
ASA Action Levels

Constituent	Action Level	Reported Units
Benzene	22000	UG/KG
Toluene	16000000	UG/KG
Ethylbenzene	7800000	UG/KG
Xylenes (Total)	160000000	UG/KG

Table 3
Ohio Action Levels

Constituent	Action Level	Reported Units
Benzene	22000	UG/KG
Toluene	16000000	UG/KG
Ethylbenzene	7800000	UG/KG
Xylenes (Total)	160000000	UG/KG
PCB, Total	1000	UG/KG

LIST OF ACRONYMS

AGT Above Ground Tank

AOC Administrative Order on Consent

ARW001 A-Round Removal Action Wall Sample
ASARs Active Screening Assessment Reports

BA Cubic-Yard Capacity Super Sack

BG, BKG Background Levels

BLDG Building

BRF002 B-Round Removal Action Floor Sample

BTEX Benzene, Toluene, Ethylbenzene, and Xylenes

COC Chain of Custody

Columbia Gas Transmission Corporation

CP Characterization Photograph

E East

EPA United States Environmental Protection Agency

Field Dup Field Sample Duplicate
GPS Global Positioning System

HDP Horizontal Drip

HG, Hg Mercury

HG (S) Mercury, Soil HG (W) Mercury, Water

J Estimated Analytical Value

J+ Estimated Analytical Value, Possibly Biased High
 J- Estimated Analytical Value, Possibly Biased Low

Km Kilometers

LRP Liquid Removal Point

M or m Meters

MG/KG Milligram per Kilogram
MG/L Milligram per Liter

MG/M³ Milligram per Cubic Meter MMS Mercury Measuring Station

MMSWP Mercury Measuring Station Work Plan

MVA Mercury Vapor Analyzer

N North or Tentative Identification of the Analytical Compound, depending on context

NA or N/A Not Available or Not Applicable, depending on context

LIST OF ACRONYMS

(Continued)

ND Non-Detect Analytical Result

OVM Organic Vapor Monitor

P1 Photograph Direction Indicator

PAH Polycyclic Aromatic Hydrocarbons

PCB Polychlorinated Biphenyls
R Rejected Analytical Result

RAC/FRs Response Action Completion/Final Reports

RP Removal Action Photograph

S Soil or South, depending on context

SD001 Sediment Sample

SOLOP Shut Off-Left on Property

SS001 Surface Soil Sample

SVOC Semi-Volatile Organic Compounds

SYP Siphon

TCLP Toxicity Characteristic Leaching Procedure

TCLP, HG Toxicity Characteristic Leaching Procedure, Mercury

TPH Total Petroleum Hydrocarbons

UDP Underslung Drip

UG/KG Microgram per Kilogram
UJ Estimated Detection Limit

UNT Unnamed Tributary

UST, UT Underground Storage Tank


VDP Vertical Drip
Vis Hg Visible Mercury

VOC Volatile Organic Compounds

W Water or West, depending on context

WESTON Roy F. Weston, Inc.
WSL Work Scope List

Location Map for ASA Sampling GatherCo II Sale Area



L05001

SIPHON ON LINE J-46 AT STATION 1062+52

SUMMARY OF FINDINGS AND RECOMMENDATIONS

This report has been prepared as part of the Active Screening Assessment (ASA), as defined under the Administrative Order on Consent for Removal Actions (AOC) issued to Columbia Gas Transmission Corporation (Columbia) by the U.S. Environmental Protection Agency (EPA), Docket No. III-94-35-DC. An ASAR is submitted to support the removal of facilities from the Work Scope List (WSL) when information and data collected pursuant to the Active Screening Assessment Work Plan (ASAWP) for Gathering Line Liquid Removal Points (LRPs) demonstrate that no further investigation or cleanup is warranted under the AOC.

This ASAR includes the Facility Conditions Survey, Liquid Removal Point Questionnaire (if any), analytical sampling results, facility sketch(es) and facility photograph(s) for facility L05001 in accordance with the ASAWP. Please note that the facility sketch may show facilities other than L05001 due to their close proximity to each other. This report is only for facility L05001. The sample locations are shown on the sketches and are visible as colored pin flags on the photograph(s).

All analytical sampling results for L05001 are below ASA Action Levels, as shown in Table 2 and defined in the ASAWP. State Action Levels for this facility are presented in Table 3 as defined by the Ohio Environmental Protection Agency. The documentation presented in this report demonstrates that Columbia characterized and performed a response action at facility L05001 pursuant to the ASAWP and that no further investigation or cleanup is warranted under the AOC for this facility. Therefore, Columbia requests that facility L05001 be removed from the WSL pursuant to Section 8.5(d) of the AOC.

Facility ID:	L05001 Facility Description:	SIPHON ON LINE J-46 AT STATION 1062+52
Facility Type:	LRP Latitude: 40° 15' 47.7" N	
Survey Date:	7/29/98 Longitude: 82° 02' 48.6" W	
A. GENERAL INFO	 Township/City: JEFFERSON TOWNSHIP County: Coshocton State: Ohio Area: OHIO 	5. District: CENTRAL 6. Operating Location: HOMER 7. Pipeline Number: J-46 8. Well Number: N/A
	4. Alea. Office	o. Well Nullioer.
B. GENERAL FACILITY FEATURES	 9. Description of Facility Topography: Sloping 10. Soil Type of local exposures: Clay Local Local Expression of predominant surrounding vegetation type: Forest 11. Description of predominant surrounding vegetation type: Forest 12. Description of nearby surface water: Name: NONE VISIBLE FROM SITE Distance: % slope: Type: Subtype: Size: 13. Drainage pathways visible? NO 14. Are surrounding lands jurisdictional wetlands? NO 15. Accessibility of the site for characterization and remediation, if required. Nearest utilities less than 1/4 mile? 17. Is cellular telephone service available? 18. Is overnight shipper nearby? (i.e. Federal Express) 	
	19. Are there any overhead obstructions that would affect remediation?	YES, TREE LIMBS
C. ADJACENT LAND USE	20. Surrounding land use: Residential 21. Approximate distance to nearby occupied structures (ft): 25 22. Evidence of public water services? NO	
D. EVIDENCE	23. Evidence of soil staining: NO	
OF A RELEASE	24. Surrounding vegetation stressed or discolored? NO	
FROM AN LRP OR ASSOCIATED FEATURES	 25. Evidence of release to nearby surface water? NO (e.g. oily sheen on top of surface water or along bank) 26. Has a release to the ground occurred at this facility? NO 	
	27. Approximate size of impacted area (sq ft):	

	Facility ID: L05001
E. MMS	28. Type of Meter Station:
EVIDENCE OF A	29. Number of meters:
RELEASE	30. Describe the housing:
	31. Flooring:
	32. Number of doorways:
	33. Evidence of mercury on soil surface?
	34. Evidence of release in building?
	35. MVA reading inside doorway:
	36. Has a release to the ground occurred at this facility?
	37. Approximate size of impacted area (sq ft):
F. STORAGE	38. Evidence of soil staining?
WELL EVIDENCE	39. Surrounding vegetation stressed or discolored?
OF A	40. Evidence of release to nearby surface water?
RELEASE	41. Evidence of discharge at wellhead annulus?
	42. Nearby seeps with discharge and/or odor:
	43. Approximate size of impacted area (sq ft):

Columbia Gas Transmission Corporation Liquid Removal Point Screening Questionnaire

Employee Name: Aaron Gaskins	RFW Facility ID: L05001
Date: 7/29/98 09:52:46	Columbia Facility Name, if any:
	Latitude: 40° 15' 47.7" N
	Longitude: 82° 02' 48.6" W
1. Removal point name: SIPHON ON LINE J-46	10. Pipeline number: J-46
2. Township/city: JEFFERSON TOWNSHIP	11. Associated well number: N/A
3. County: Coshocton	12a. Associated metering station number: N/A
4. State: Ohio	12b. Is this or was this a Mercury Metering Station?
5. Area: OHIO	13a. Inventory station number: 1062+52
omo	13b. Inventory map number: 4456+408
6. District: CENTRAL	14. Is the removal point on a backfed system? NO
7. Operating location:	
HOMER	15. How much liquid (gallons/year) has this removal point historically produced? 0
8. Removal point type: Liquid Removal Point	16. If the removal point produced liquids, how often were the liquids collected historically? Never
9. Removal point function: TRANSMISSION	17. Approximately how many years has this removal point been in operation? 4
	18. Approximately how many years have fluids been produced? N/A
	19. Is there knowledge of a release to the ground at this site? NO
	This release is associated with:
20a. How much liquid (gallons/year) has been released to the ground historical	ly? 0
20b. Historical discharge characteristics:	
NONE	
21. If the removal point produced liquids, how often were these liquids releas	ed to the ground historically? Never
22. If liquid releases have been identified in 19,20, or 21, what has been relea	sed?
23a. Has an historical, atypical release occurred at this site?	
23b. How much liquid (gallons) was released?	
23c. How many years ago was this release?	
24a. Are storage tanks associated with removal point? NO	
24b. Number of years since tank installation?	
25. Other surface or subsurface features associated with removal point:	

Columbia Gas Transmission Corporation Liquid Removal Point Screening Questionnaire

RFW Facility ID: L05001		
26. Evidence of soil staining:	NO	
The staining is associated with:		
27. Evidence of stressed vegetation:	NO	
The evidence is associated with:		
28. Approximate size of release are:		
29. Are there any nearby waterbodies:	NO	
Approximate distance to waterbody:		
30. (Reserved for Site Sketch.)		
31. (Reserved for LRP Photograph.)		
32. Site Access Restrictions:	Road Available; 4 WD Required	
Distance from main road:	100 ft. to 1/4 Mile	

Analytical Results Facility ID: L05001

			Analysis				Detection	
Field Sample ID	Matrix	Collected		Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05001-SS001-40001	S	7/29/98	GC BTEX(S)	BENZENE	ND		5.6	UG/KC
L05001-SS001-40001	S	7/29/98	GC BTEX(S)	ETHYL BENZENE	ND		5.6	UG/KC
L05001-SS001-40001	S	7/29/98	GC BTEX(S)	TOLUENE	ND		5.6	UG/KC
L05001-SS001-40001	S	7/29/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.6	UG/KC
L05001-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1016	ND		37	UG/KC
L05001-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1221	ND		37	UG/KC
L05001-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1232	ND		37	UG/KC
L05001-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1242	ND		37	UG/KC
L05001-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1248	ND		37	UG/KC
L05001-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1254	ND		37	UG/KC
L05001-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1260	ND		37	UG/KC
L05001-SS001-41001 (Field Dup)	S	7/29/98	GC BTEX(S)	BENZENE	ND		5.7	UG/KC
L05001-SS001-41001 (Field Dup)	S	7/29/98	GC BTEX(S)	ETHYL BENZENE	ND		5.7	UG/KC
L05001-SS001-41001 (Field Dup)	S	7/29/98	GC BTEX(S)	TOLUENE	ND		5.7	UG/KC
L05001-SS001-41001 (Field Dup)	S	7/29/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.7	UG/KC
L05001-SS001-41001 (Field Dup)	S	7/29/98	PCB(S)	AROCLOR-1016	ND		38	UG/KC
L05001-SS001-41001 (Field Dup)	S	7/29/98	PCB(S)	AROCLOR-1221	ND		38	UG/KC
L05001-SS001-41001 (Field Dup)	S	7/29/98	PCB(S)	AROCLOR-1232	ND		38	UG/KC
L05001-SS001-41001 (Field Dup)	S	7/29/98	PCB(S)	AROCLOR-1242	ND		38	UG/KC
L05001-SS001-41001 (Field Dup)	S	7/29/98	PCB(S)	AROCLOR-1248	ND		38	UG/KC
L05001-SS001-41001 (Field Dup)	S	7/29/98	PCB(S)	AROCLOR-1254	ND		38	UG/KC
L05001-SS001-41001 (Field Dup)	S	7/29/98	PCB(S)	AROCLOR-1260	ND		38	UG/KC

Analytical Results Facility ID: L05001

			Analysis				Detection	
Field Sample ID	Matrix	Collected	Category	Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05001-SS002-40001	S	7/29/98	GC BTEX(S)	BENZENE	ND		5.4	UG/KG
L05001-SS002-40001	S	7/29/98	GC BTEX(S)	ETHYL BENZENE	ND		5.4	UG/KG
L05001-SS002-40001	S	7/29/98	GC BTEX(S)	TOLUENE	ND		5.4	UG/KG
L05001-SS002-40001	S	7/29/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.4	UG/KG
L05001-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1016	ND		36	UG/KG
L05001-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1221	ND		36	UG/KG
L05001-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1232	ND		36	UG/KG
L05001-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1242	ND		36	UG/KG
L05001-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1248	ND		36	UG/KG
L05001-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1254	ND		36	UG/KG
L05001-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1260	ND		36	UG/KG

^{*} Legend:

J=Estimated Analytical Value UJ=Estimated Detection Limit J+ =Estimated Analytical Value, Possible Biased High J- =Estimated Analytical Value, Possibly Biased Low


R=Rejected Result



Facility ID: L05001 Photo Date:07/29/98 10:13 SIPHON ON LINE J-46 AT STATION 1062+52



Facility ID: L05001 Photo Date:07/29/98 10:13 SIPHON ON LINE J-46 AT STATION 1062+52



L05002

HORIZONTAL DRIP ON LINE J

SUMMARY OF FINDINGS AND RECOMMENDATIONS

This report has been prepared as part of the Active Screening Assessment (ASA), as defined under the Administrative Order on Consent for Removal Actions (AOC) issued to Columbia Gas Transmission Corporation (Columbia) by the U.S. Environmental Protection Agency (EPA), Docket No. III-94-35-DC. An ASAR is submitted to support the removal of facilities from the Work Scope List (WSL) when information and data collected pursuant to the Active Screening Assessment Work Plan (ASAWP) for Gathering Line Liquid Removal Points (LRPs) demonstrate that no further investigation or cleanup is warranted under the AOC.

This ASAR includes the Facility Conditions Survey, Liquid Removal Point Questionnaire (if any), analytical sampling results, facility sketch(es) and facility photograph(s) for facility L05002 in accordance with the ASAWP. Please note that the facility sketch may show facilities other than L05002 due to their close proximity to each other. This report is only for facility L05002. The sample locations are shown on the sketches and are visible as colored pin flags on the photograph(s).

All analytical sampling results for L05002 are below ASA Action Levels, as shown in Table 2 and defined in the ASAWP. State Action Levels for this facility are presented in Table 3 as defined by the Ohio Environmental Protection Agency. The documentation presented in this report demonstrates that Columbia characterized and performed a response action at facility L05002 pursuant to the ASAWP and that no further investigation or cleanup is warranted under the AOC for this facility. Therefore, Columbia requests that facility L05002 be removed from the WSL pursuant to Section 8.5(d) of the AOC.

Facility ID:	L05002 Facility Description: H	ORIZONTAL DRIP ON LINE J
Facility Type:	LRP Latitude: 40° 15' 41.2" N	
Survey Date:	7/29/98 Longitude: 82° 04' 35.7" W	
A. GENERAL INFO	1. Township/City: BEDFORD TOWNSHIP 2. County: Coshocton	5. District: CENTRAL 6. Operating Location: HOMER
	3. State: Ohio	7. Pipeline Number: J
	4. Area: OHIO	8. Well Number: N/A
B. GENERAL FACILITY FEATURES	9. Description of Facility Topography: 10. Soil Type of local exposures: 11. Description of predominant surrounding vegetation type: 12. Description of nearby surface water: Name: NONE VISIBLE FROM SITE Distance: % slope: Type: Subtype: Size: 13. Drainage pathways visible? NO 14. Are surrounding lands jurisdictional wetlands? NO 15. Accessibility of the site for characterization and remediation, if required in the content of the state of the characterization and remediation. If required in the content of the state of the s	ed: Road all the way to site YES, OVERHEAD LINES YES YES
C ADIACENE	19. Are there any overhead obstructions that would affect remediation?	NO
C. ADJACENT LAND USE	 20. Surrounding land use: Undeveloped 21. Approximate distance to nearby occupied structures (ft): 500 22. Evidence of public water services? NO 	Type of structure: HOUSE
D. EVIDENCE OF A RELEASE FROM AN LRP OR ASSOCIATED FEATURES	 23. Evidence of soil staining: NO 24. Surrounding vegetation stressed or discolored? NO 25. Evidence of release to nearby surface water? NO (e.g. oily sheen on top of surface water or along bank) 26. Has a release to the ground occurred at this facility? NO POSSIBLY IN THE PAST, BUT NOT TO GUIDE'S KNOWLEDGE 27. Approximate size of impacted area (sq ft): 	GE

	Facility ID: L05002
E. MMS EVIDENCE OF A RELEASE	28. Type of Meter Station: 29. Number of meters: 30. Describe the housing: 31. Flooring: 32. Number of doorways: 33. Evidence of mercury on soil surface? 34. Evidence of release in building? 35. MVA reading inside doorway: 36. Has a release to the ground occurred at this facility?
F. STORAGE WELL EVIDENCE OF A RELEASE	 37. Approximate size of impacted area (sq ft): 38. Evidence of soil staining? 39. Surrounding vegetation stressed or discolored? 40. Evidence of release to nearby surface water? 41. Evidence of discharge at wellhead annulus? 42. Nearby seeps with discharge and/or odor: 43. Approximate size of impacted area (sq ft):

Columbia Gas Transmission Corporation Liquid Removal Point Screening Questionnaire

Employee Name: Aaron Gaskins	RFW Facility ID: L05002	
Date: 7/29/98 11:37:52	Columbia Facility Name, if any:	
	Latitude: 40° 15' 41.2" N	
	Longitude: 82° 04' 35.7" W	
1. Removal point name: HORIZONTAL DRIP ON LINE J	10. Pipeline number: J	
2. Township/city: BEDFORD TOWNSHIP	11. Associated well number: N/A	
3. County: Coshocton	12a. Associated metering station number: N/A	
4. State: Ohio	12b. Is this or was this a Mercury Metering Station?	
5. Area: OHIO	13a. Inventory station number: N/A	
	13b. Inventory map number: 4456-408	
6. District: CENTRAL	14. Is the removal point on a backfed system? NO	
7. Operating location: HOME	15. How much liquid (gallons/year) has this removal point historically produced? $\bf 0$ - $\bf 10$	
8. Removal point type: Liquid Removal Point 16. If the removal point produced liquids, how often were the liquids collected historically? Once/Year		
9. Removal point function: TRANSMISSION	17. Approximately how many years has this removal point been in operation? >20	
	18. Approximately how many years have fluids been produced? >20	
	19. Is there knowledge of a release to the ground at this site? NO	
	This release is associated with:	
20a. How much liquid (gallons/year) has been released to the ground historically?		
20b. Historical discharge characteristics:		
NONE		
21. If the removal point produced liquids, how often were these liquids release	ed to the ground historically? Never	
22. If liquid releases have been identified in 19,20, or 21, what has been released?		
23a. Has an historical, atypical release occurred at this site?		
23b. How much liquid (gallons) was released?		
23c. How many years ago was this release?		
24a. Are storage tanks associated with removal point? NO		
24b. Number of years since tank installation?		
25. Other surface or subsurface features associated with removal point:		

Columbia Gas Transmission Corporation Liquid Removal Point Screening Questionnaire

RFW Facility ID: L05002	
26. Evidence of soil staining:	NO
The staining is associated with:	
27. Evidence of stressed vegetation:	NO
The evidence is associated with:	
28. Approximate size of release are	
29. Are there any nearby waterbodies:	NO
Approximate distance to waterbody	
30. (Reserved for Site Sketch.)	
31. (Reserved for LRP Photograph.)	
32. Site Access Restrictions:	Road All The Way To Site
Distance from main road:	Less Than 100 ft.

Analytical Results Facility ID: L05002

			Analysis				Detection	
Field Sample ID	Matrix	Collected		Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05002-SS001-40001	S	7/29/98	GC BTEX(S)	BENZENE	ND		5.7	UG/KG
L05002-SS001-40001	S	7/29/98	GC BTEX(S)	ETHYL BENZENE	ND		5.7	UG/KG
L05002-SS001-40001	S	7/29/98	GC BTEX(S)	TOLUENE	ND		5.7	UG/KG
L05002-SS001-40001	S	7/29/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.7	UG/KG
L05002-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1016	ND		38	UG/KG
L05002-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1221	ND		38	UG/KG
L05002-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1232	ND		38	UG/KG
L05002-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1242	ND		38	UG/KG
L05002-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1248	ND		38	UG/KG
L05002-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1254	ND		38	UG/KG
L05002-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1260	ND		38	UG/KG
L05002-SS002-40001	S	7/29/98	GC BTEX(S)	BENZENE	ND		5.9	UG/KG
L05002-SS002-40001	S	7/29/98	GC BTEX(S)	ETHYL BENZENE	ND		5.9	UG/KG
L05002-SS002-40001	S	7/29/98	GC BTEX(S)	TOLUENE	ND		5.9	UG/KG
L05002-SS002-40001	S	7/29/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.9	UG/KG
L05002-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1016	ND		39	UG/KG
L05002-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1221	ND		39	UG/KG
L05002-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1232	ND		39	UG/KG
L05002-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1242	ND		39	UG/KG
L05002-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1248	ND		39	UG/KG
L05002-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1254	ND		39	UG/KG
L05002-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1260	ND		39	UG/KG

^{*} Legend:

J=Estimated Analytical Value UJ=Estimated Detection Limit J+ =Estimated Analytical Value, Possible Biased High J- =Estimated Analytical Value, Possibly Biased Low

R=Rejected Result



Facility ID: L05002 Photo Date:07/29/98 11:57 HORIZONTAL DRIP ON LINE J



Facility ID: L05002 Photo Date:07/29/98 11:57 HORIZONTAL DRIP ON LINE J

Facility ID: L05002 Sketch 1 of 1 VESTON FACILITY ID: LOSOO2 & SAMPLE DATE: 7/29/98 SKETCHED BY: A, Gaskin S L05003 COLUMBIA FACILITY ID/DESCRIPTION: 2 Horizontal Drips on Line J (Station unknown) To house ~500° L05002 5 Q. HORIZONTAL DRIP **⊗ ©** \$5001 L05003 @→ End of Horizontal Flat OX SSGC2 Drip to: SS001-0'4" Marker orange Meta 55002-514" Cover Flat Line Marker 5 to: 55001-67" -> OLINE SS002-10'0" oLine Marker Road Marker l is ر 15′ U Tall plants & Tall plants wide some trees & some trees 75 **@** L05002 End of a i Horizontal M) Drip to: Flat SS001+0'0" SS002+5'0" B Marker -05003 LORIZONTAL 2 DRIP XO Center of Orange Metal \$500I L cover to: 1 1SS002 S\$001+Z'3' 0) \$\$002+4'7" O. کر S 0 ٥ **(**P2) X = measurement location SS001 (SAMPLE LOC.) Х Y REMINDERS YYYYY SLOPE **¶**NORTH ARROW ==== DIRT/GRAVEL RD SS001 75CL ¶ROAD NAMES ☐ ☆ GAS WELL PAVED ROAD SS002 **I OVERHEAD LINES** - UNDRGD PIPELINE M PHOTO DIRECTION X Υ LINE MARKERS EXPOSED PIPELINE SS001 1 OCCUPIED STRUCTURES M APPROX. SCALE: 1 block = 2 ft.2 ======= STREAM/CREEK) BUILDINGS SS002) SURFACE WATERS → DIRECTION OF FLOW

L05003 HORIZONTAL DRIP ON LINE J

SUMMARY OF FINDINGS AND RECOMMENDATIONS

This report has been prepared as part of the Active Screening Assessment (ASA), as defined under the Administrative Order on Consent for Removal Actions (AOC) issued to Columbia Gas Transmission Corporation (Columbia) by the U.S. Environmental Protection Agency (EPA), Docket No. III-94-35-DC. An ASAR is submitted to support the removal of facilities from the Work Scope List (WSL) when information and data collected pursuant to the Active Screening Assessment Work Plan (ASAWP) for Gathering Line Liquid Removal Points (LRPs) demonstrate that no further investigation or cleanup is warranted under the AOC.

This ASAR includes the Facility Conditions Survey, Liquid Removal Point Questionnaire (if any), analytical sampling results, facility sketch(es) and facility photograph(s) for facility L05003 in accordance with the ASAWP. Please note that the facility sketch may show facilities other than L05003 due to their close proximity to each other. This report is only for facility L05003. The sample locations are shown on the sketches and are visible as colored pin flags on the photograph(s).

All analytical sampling results for L05003 are below ASA Action Levels, as shown in Table 2 and defined in the ASAWP. State Action Levels for this facility are presented in Table 3 as defined by the Ohio Environmental Protection Agency. The documentation presented in this report demonstrates that Columbia characterized and performed a response action at facility L05003 pursuant to the ASAWP and that no further investigation or cleanup is warranted under the AOC for this facility. Therefore, Columbia requests that facility L05003 be removed from the WSL pursuant to Section 8.5(d) of the AOC.

Facility ID:	L05003 Facility Description: F	IORIZONTAL DRIP ON LINE J				
Facility Type:	LRP Latitude: 40° 15' 41.0" N					
Survey Date:	7/29/98 Longitude: 82° 04' 35.4" W					
A. GENERAL INFO	Township/City: BEDFORD TOWNSHIP County: Coshocton	5. District: CENTRAL 6. Operating Location: HOMER				
	3. State: Ohio	7. Pipeline Number: J				
	4. Area: OHIO	8. Well Number: N/A				
	4. Alea. Office	o. Well Nulliber.				
B. GENERAL FACILITY FEATURES	 Description of Facility Topography: Gently 5 Soil Type of local exposures: Clay Lo Description of predominant surrounding vegetation type: Shrub 	Sloping (3 - 8 % slope) am				
	12. Description of nearby surface water: Name: NONE VISIBLE FROM SITE Distance: % slope: Type: Subtype: Size:					
	13. Drainage pathways visible? NO					
	14. Are surrounding lands jurisdictional wetlands? NO					
	 15. Accessibility of the site for characterization and remediation, if required: Road all the way to site 16. Nearest utilities less than 1/4 mile? YES, OVERHEAD LINES 					
	17. Is cellular telephone service available? YES					
	18. Is overnight shipper nearby? (i.e. Federal Express)	YES				
	19. Are there any overhead obstructions that would affect remediation?	NO				
C. ADJACENT	20. Surrounding land use: Undeveloped					
LAND USE	21. Approximate distance to nearby occupied structures (ft): 556	Type of structure: HOUSE				
	22. Evidence of public water services? NO					
D. EVIDENCE	23. Evidence of soil staining: NO					
OF A RELEASE FROM AN LRP OR ASSOCIATED FEATURES	24. Surrounding vegetation stressed or discolored? NO					
	25. Evidence of release to nearby surface water? NO (e.g. oily sheen on top of surface water or along bank)					
	26. Has a release to the ground occurred at this facility? NO POSSIBLY IN THE PAST, BUT NOT TO GUIDE'S KNOWLEDGE					
	27. Approximate size of impacted area (sq ft):					

	Facility ID: L05003				
E. MMS	71				
EVIDENCE OF A	29. Number of meters:				
RELEASE	30. Describe the housing:				
	31. Flooring:				
	32. Number of doorways:				
	33. Evidence of mercury on soil surface?				
	34. Evidence of release in building?				
	35. MVA reading inside doorway:				
	36. Has a release to the ground occurred at this facility?				
	37. Approximate size of impacted area (sq ft):				
F. STORAGE	38. Evidence of soil staining?				
WELL EVIDENCE	39. Surrounding vegetation stressed or discolored?				
OF A	40. Evidence of release to nearby surface water?				
RELEASE	41. Evidence of discharge at wellhead annulus?				
	42. Nearby seeps with discharge and/or odor:				
	43. Approximate size of impacted area (sq ft):				

Columbia Gas Transmission Corporation Liquid Removal Point Screening Questionnaire

Employee Name: Aaron Gaskins	RFW Facility ID: L05003	
Date: 7/29/98 11:41:43	Columbia Facility Name, if any:	
	Latitude: 40° 15' 41.0" N	
	Longitude: 82° 04' 35.4" W	
1. Removal point name: HORIZONTAL DRIP ON LINE J	10. Pipeline number: J	
2. Township/city: BEDFORD TOWNSHIP	11. Associated well number: N/A	
3. County: Coshocton	12a. Associated metering station number: N/A	
4. State: Ohio	12b. Is this or was this a Mercury Metering Station?	
5. Area: OHIO	13a. Inventory station number: N/A	
	13b. Inventory map number: 4456-408	
6. District: CENTRAL	14. Is the removal point on a backfed system? NO	
7. Operating location: HOMER	15. How much liquid (gallons/year) has this removal point historically produced? 0 - 10	
3. Removal point type: Liquid Removal Point 16. If the removal point produced liquids, how often were the liquids collected historically? Once/Year		
9. Removal point function: TRANSMISSION	17. Approximately how many years has this removal point been in operation? >20	
	18. Approximately how many years have fluids been produced? >20	
	19. Is there knowledge of a release to the ground at this site?	
	This release is associated with:	
20a. How much liquid (gallons/year) has been released to the ground historically?		
20b. Historical discharge characteristics:		
NONE		
21. If the removal point produced liquids, how often were these liquids releas	ed to the ground historically? Never	
22. If liquid releases have been identified in 19,20, or 21, what has been released?		
23a. Has an historical, atypical release occurred at this site?		
23b. How much liquid (gallons) was released?		
23c. How many years ago was this release?		
24a. Are storage tanks associated with removal point? NO		
24b. Number of years since tank installation?		
25. Other surface or subsurface features associated with removal point:		

RFW Facility ID: L05003	
26. Evidence of soil staining:	NO
The staining is associated with:	
27. Evidence of stressed vegetation:	NO
The evidence is associated with:	
28. Approximate size of release are:	
29. Are there any nearby waterbodies:	NO
Approximate distance to waterbody:	
30. (Reserved for Site Sketch.)	
31. (Reserved for LRP Photograph.)	
32. Site Access Restrictions:	Road All The Way To Site
Distance from main road:	Less Than 100 ft.

Analytical Results Facility ID: L05003

			Analysis				Detection	
Field Sample ID	Matrix	Collected	Category	Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05003-SS001-40001	S	7/29/98	GC BTEX(S)	BENZENE	ND		6.0	UG/KG
L05003-SS001-40001	S	7/29/98	GC BTEX(S)	ETHYL BENZENE	ND		6.0	UG/KG
L05003-SS001-40001	S	7/29/98	GC BTEX(S)	TOLUENE	ND		6.0	UG/KG
L05003-SS001-40001	S	7/29/98	GC BTEX(S)	XYLENES (TOTAL)	ND		6.0	UG/KG
L05003-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1016	ND		39	UG/KG
L05003-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1221	ND		39	UG/KG
L05003-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1232	ND		39	UG/KG
L05003-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1242	ND		39	UG/KG
L05003-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1248	ND		39	UG/KG
L05003-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1254	ND		39	UG/KG
L05003-SS001-40001	S	7/29/98	PCB(S)	AROCLOR-1260	ND		39	UG/KG
L05003-SS002-40001	S	7/29/98	GC BTEX(S)	BENZENE	ND		5.8	UG/KG
L05003-SS002-40001	S	7/29/98	GC BTEX(S)	ETHYL BENZENE	ND		5.8	UG/KG
L05003-SS002-40001	S	7/29/98	GC BTEX(S)	TOLUENE	ND		5.8	UG/KG
L05003-SS002-40001	S	7/29/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.8	UG/KG
L05003-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1016	ND		38	UG/KG
L05003-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1221	ND		38	UG/KG
L05003-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1232	ND		38	UG/KG
L05003-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1242	ND		38	UG/KG
L05003-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1248	ND		38	UG/KG
L05003-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1254	ND		38	UG/KG
L05003-SS002-40001	S	7/29/98	PCB(S)	AROCLOR-1260	ND		38	UG/KG

^{*} Legend:

J=Estimated Analytical Value UJ=Estimated Detection Limit J+ =Estimated Analytical Value, Possible Biased High J- =Estimated Analytical Value, Possibly Biased Low

R=Rejected Result



Facility ID: L05003 Photo Date:07/29/98 11:58 HORIZONTAL DRIP ON LINE J



Facility ID: L05003 Photo Date:07/29/98 11:58 HORIZONTAL DRIP ON LINE J

Facility ID: L05003 Sketch 1 of 1 VESTON FACILITY ID: LOSOO2 & SAMPLE DATE: 7/29/98 SKETCHED BY: A. Gaskin S L05003 COLUMBIA FACILITY ID/DESCRIPTION: 2 Horizontal Drips on Line J (Station unknown) To house ~500° L05002 5 Q. HORIZONTAL DRIP **⊗ ©** \$5001 L05003 @→ End of Horizontal Flat OX SSGC2 Drip to: SS001-0'4" Marker orange Meta 55002-514" Cover Flat Line Marker 5 to: 55001-67" -> OLINE SS002-10'0" oLine Marker Road Marker l is ر 15′ U Tall plants & Tali plants wide some trees & some trees 75 **@** L05002 End of a i Horizontal M) Drip to: Flat SS001+0'0" SS002+5'0" B Marker -05003 LORIZONTAL 2 DRIP XO Center of Orange Metal \$500I L cover to: 1 1SS002 S\$001+Z'3' 0) \$\$002+4'7" O. کر S 0 ٥ **(**P2) X = measurement location SS001 (SAMPLE LOC.) Х Υ REMINDERS YYYYY SLOPE **¶**NORTH ARROW === = DIRT/GRAVEL RD SS001 75CL ¶ROAD NAMES ☐ ☆ GAS WELL PAVED ROAD SS002 **I OVERHEAD LINES** - UNDRGD PIPELINE M PHOTO DIRECTION X Υ LINE MARKERS EXPOSED PIPELINE SS001 1 OCCUPIED STRUCTURES M APPROX. SCALE: 1 block = 2 ft.2 ======= STREAM/CREEK) BUILDINGS SS002) SURFACE WATERS → DIRECTION OF FLOW

L05004

HORIZONTAL DRIP ON LINE J AT STATION 1114+80

SUMMARY OF FINDINGS AND RECOMMENDATIONS

This report has been prepared as part of the Active Screening Assessment (ASA), as defined under the Administrative Order on Consent for Removal Actions (AOC) issued to Columbia Gas Transmission Corporation (Columbia) by the U.S. Environmental Protection Agency (EPA), Docket No. III-94-35-DC. An ASAR is submitted to support the removal of facilities from the Work Scope List (WSL) when information and data collected pursuant to the Active Screening Assessment Work Plan (ASAWP) for Gathering Line Liquid Removal Points (LRPs) demonstrate that no further investigation or cleanup is warranted under the AOC.

This ASAR includes the Facility Conditions Survey, Liquid Removal Point Questionnaire (if any), analytical sampling results, facility sketch(es) and facility photograph(s) for facility L05004 in accordance with the ASAWP. Please note that the facility sketch may show facilities other than L05004 due to their close proximity to each other. This report is only for facility L05004. The sample locations are shown on the sketches and are visible as colored pin flags on the photograph(s).

All analytical sampling results for L05004 are below ASA Action Levels, as shown in Table 2 and defined in the ASAWP. State Action Levels for this facility are presented in Table 3 as defined by the Ohio Environmental Protection Agency. The documentation presented in this report demonstrates that Columbia characterized and performed a response action at facility L05004 pursuant to the ASAWP and that no further investigation or cleanup is warranted under the AOC for this facility. Therefore, Columbia requests that facility L05004 be removed from the WSL pursuant to Section 8.5(d) of the AOC.

Facility ID:	L05004 Facility Description: H	ORIZONTAL DRIP ON LINE J AT STATION 1114+80		
Facility Type:	LRP Latitude: 40° 15' 45.1" N			
Survey Date:	8/4/98 Longitude: 82° 03' 38.4" W			
A. GENERAL INFO	 Township/City: BEDFORD TOWNSHIP County: Coshocton 	5. District: CENTRAL 6. Operating Location: HOMER		
	3. State: Ohio	7. Pipeline Number: J		
	4. Area: OHIO	8. Well Number: N/A		
B. GENERAL FACILITY FEATURES	9. Description of Facility Topography: 10. Soil Type of local exposures: Sandy L 11. Description of predominant surrounding vegetation type: Forest 12. Description of nearby surface water: Name: NONE VISIBLE FROM SITE Distance: % slope: Type: Subtype: Size: 13. Drainage pathways visible? NO 14. Are surrounding lands jurisdictional wetlands? NO 15. Accessibility of the site for characterization and remediation, if required. 16. Nearest utilities less than 1/4 mile? 17. Is cellular telephone service available? 18. Is overnight shipper nearby? (i.e. Federal Express)			
	19. Are there any overhead obstructions that would affect remediation?	YES, TREES		
C. ADJACENT LAND USE	20. Surrounding land use: Undeveloped 21. Approximate distance to nearby occupied structures (ft): 200 22. Evidence of public water services? NO			
D. EVIDENCE OF A RELEASE FROM AN LRP OR ASSOCIATED FEATURES	 23. Evidence of soil staining: NO 24. Surrounding vegetation stressed or discolored? NO 25. Evidence of release to nearby surface water? NO (e.g. oily sheen on top of surface water or along bank) 26. Has a release to the ground occurred at this facility? NO POSSIBLY IN THE PAST, BUT NOT TO GUIDE'S KNOWLEDGE 27. Approximate size of impacted area (sq ft): 	GE		

	Facility ID: L05004
E. MMS	28. Type of Meter Station:
EVIDENCE OF A	29. Number of meters:
RELEASE	30. Describe the housing:
	31. Flooring:
	32. Number of doorways:
	33. Evidence of mercury on soil surface?
	34. Evidence of release in building?
	35. MVA reading inside doorway:
	36. Has a release to the ground occurred at this facility?
	37. Approximate size of impacted area (sq ft):
F. STORAGE	38. Evidence of soil staining?
WELL EVIDENCE	39. Surrounding vegetation stressed or discolored?
OF A	40. Evidence of release to nearby surface water?
RELEASE	41. Evidence of discharge at wellhead annulus?
	42. Nearby seeps with discharge and/or odor:
	43. Approximate size of impacted area (sq ft):

Employee Name: Aaron Gaskins	RFW Facility ID: L05004	
Date: 8/4/98 09:15:13	Columbia Facility Name, if any:	
	Latitude: 40° 15' 45.1" N	
	Longitude: 82° 03' 38.4" W	
1. Removal point name: DRIP ON LINE J	10. Pipeline number: J	
2. Township/city: BEDFORD TOWNSHIP	11. Associated well number: N/A	
3. County: Coshocton	12a. Associated metering station number: N/A	
4. State: Ohio	12b. Is this or was this a Mercury Metering Station?	
5. Area: OHIO	13a. Inventory station number: 1114+80	
	13b. Inventory map number: 4456-408	
6. District: CENTRAL	14. Is the removal point on a backfed system? NO	
7. Operating location: HOMER	15. How much liquid (gallons/year) has this removal point historically produced? 0 - 10	
8. Removal point type: Liquid Removal Point	16. If the removal point produced liquids, how often were the liquids collected historically? Once/Year	
9. Removal point function: TRANSMISSION	17. Approximately how many years has this removal point been in operation? >20	
	18. Approximately how many years have fluids been produced? >20	
	19. Is there knowledge of a release to the ground at this site? NO	
	This release is associated with:	
20a. How much liquid (gallons/year) has been released to the ground historically?		
20b. Historical discharge characteristics:		
NONE		
21. If the removal point produced liquids, how often were these liquids releas	ed to the ground historically? Never	
22. If liquid releases have been identified in 19,20, or 21, what has been relea	sed?	
23a. Has an historical, atypical release occurred at this site?	<u> </u>	
23b. How much liquid (gallons) was released?		
23c. How many years ago was this release?		
24a. Are storage tanks associated with removal point? NO		
24b. Number of years since tank installation?		
25. Other surface or subsurface features associated with removal point:		

RFW Facility ID: L05004		
26. Evidence of soil staining:	NO	
The staining is associated with:		
27. Evidence of stressed vegetation:	NO	
The evidence is associated with:		
28. Approximate size of release are:		
29. Are there any nearby waterbodies:	NO	
Approximate distance to waterbody	:	
30. (Reserved for Site Sketch.)		
31. (Reserved for LRP Photograph.)		
32. Site Access Restrictions:	Road Available; 4 WD Required	
Distance from main road:	Less Than 100 ft.	

Analytical Results Facility ID: L05004

			Analysis				Detection	
Field Sample ID	Matrix	Collected		Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05004-SS001-40001	S	8/4/98	GC BTEX(S)	BENZENE	6.5	UJ	6.5	UG/KC
L05004-SS001-40001	S	8/4/98	GC BTEX(S)	ETHYL BENZENE	6.5	UJ	6.5	UG/KC
L05004-SS001-40001	S	8/4/98	GC BTEX(S)	TOLUENE	6.5	UJ	6.5	UG/KC
L05004-SS001-40001	S	8/4/98	GC BTEX(S)	XYLENES (TOTAL)	6.5	UJ	6.5	UG/KC
L05004-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1016	ND		43	UG/KC
L05004-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1221	ND		43	UG/KC
L05004-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1232	ND		43	UG/KC
L05004-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1242	ND		43	UG/KC
L05004-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1248	ND		43	UG/KC
L05004-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1254	ND		43	UG/KC
L05004-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1260	ND		43	UG/KC
L05004-SS001-41001 (Field Dup)	S	8/4/98	GC BTEX(S)	BENZENE	5.9	UJ	5.9	UG/KC
L05004-SS001-41001 (Field Dup)	S	8/4/98	GC BTEX(S)	ETHYL BENZENE	5.9	UJ	5.9	UG/KC
L05004-SS001-41001 (Field Dup)	S	8/4/98	GC BTEX(S)	TOLUENE	5.9	UJ	5.9	UG/KC
L05004-SS001-41001 (Field Dup)	S	8/4/98	GC BTEX(S)	XYLENES (TOTAL)	7.3	J	5.9	UG/KC
L05004-SS001-41001 (Field Dup)	S	8/4/98	PCB(S)	AROCLOR-1016	ND		39	UG/KC
L05004-SS001-41001 (Field Dup)	S	8/4/98	PCB(S)	AROCLOR-1221	ND		39	UG/KC
L05004-SS001-41001 (Field Dup)	S	8/4/98	PCB(S)	AROCLOR-1232	ND		39	UG/KC
L05004-SS001-41001 (Field Dup)	S	8/4/98	PCB(S)	AROCLOR-1242	ND		39	UG/KC
L05004-SS001-41001 (Field Dup)	S	8/4/98	PCB(S)	AROCLOR-1248	ND		39	UG/KC
L05004-SS001-41001 (Field Dup)	S	8/4/98	PCB(S)	AROCLOR-1254	ND		39	UG/KC
L05004-SS001-41001 (Field Dup)	S	8/4/98	PCB(S)	AROCLOR-1260	ND		39	UG/KC

Analytical Results Facility ID: L05004

			Analysis				Detection	
Field Sample ID	Matrix	Collected	Category	Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05004-SS002-40001	S	8/4/98	GC BTEX(S)	BENZENE	ND		5.9	UG/KG
L05004-SS002-40001	S	8/4/98	GC BTEX(S)	ETHYL BENZENE	ND		5.9	UG/KG
L05004-SS002-40001	S	8/4/98	GC BTEX(S)	TOLUENE	ND		5.9	UG/KG
L05004-SS002-40001	S	8/4/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.9	UG/KG
L05004-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1016	ND		39	UG/KG
L05004-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1221	ND		39	UG/KG
L05004-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1232	ND		39	UG/KG
L05004-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1242	ND		39	UG/KG
L05004-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1248	ND		39	UG/KG
L05004-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1254	ND		39	UG/KG
L05004-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1260	ND		39	UG/KG

^{*} Legend:

J=Estimated Analytical Value UJ=Estimated Detection Limit J+ =Estimated Analytical Value, Possible Biased High J- =Estimated Analytical Value, Possibly Biased Low

R=Rejected Result



Facility ID: L05004 Photo Date:08/04/98 10:18 HORIZONTAL DRIP ON LINE J AT STATION 1114+80



Facility ID: L05004 Photo Date:08/04/98 10:18 HORIZONTAL DRIP ON LINE J AT STATION 1114+80

L05005

HORIZONTAL DRIP ON LINE J AT STATION 1149+93

SUMMARY OF FINDINGS AND RECOMMENDATIONS

This report has been prepared as part of the Active Screening Assessment (ASA), as defined under the Administrative Order on Consent for Removal Actions (AOC) issued to Columbia Gas Transmission Corporation (Columbia) by the U.S. Environmental Protection Agency (EPA), Docket No. III-94-35-DC. An ASAR is submitted to support the removal of facilities from the Work Scope List (WSL) when information and data collected pursuant to the Active Screening Assessment Work Plan (ASAWP) for Gathering Line Liquid Removal Points (LRPs) demonstrate that no further investigation or cleanup is warranted under the AOC.

This ASAR includes the Facility Conditions Survey, Liquid Removal Point Questionnaire (if any), analytical sampling results, facility sketch(es) and facility photograph(s) for facility L05005 in accordance with the ASAWP. Please note that the facility sketch may show facilities other than L05005 due to their close proximity to each other. This report is only for facility L05005. The sample locations are shown on the sketches and are visible as colored pin flags on the photograph(s).

All analytical sampling results for L05005 are below ASA Action Levels, as shown in Table 2 and defined in the ASAWP. State Action Levels for this facility are presented in Table 3 as defined by the Ohio Environmental Protection Agency. The documentation presented in this report demonstrates that Columbia characterized and performed a response action at facility L05005 pursuant to the ASAWP and that no further investigation or cleanup is warranted under the AOC for this facility. Therefore, Columbia requests that facility L05005 be removed from the WSL pursuant to Section 8.5(d) of the AOC.

Facility ID:	L05005 Facility Description: I	IORIZONTAL DRIP ON LINE J AT STATION 1149+93					
Facility Type:	LRP Latitude:						
Survey Date:	8/4/98 Longitude:						
A. GENERAL INFO	Township/City: BEDFORD County: Coshocton	5. District: CENTRAL 6. Operating Location: HOMER					
	3. State: Ohio	7. Pipeline Number: J					
	4. Area: OHIO	8. Well Number: N/A					
B. GENERAL FACILITY FEATURES	9. Description of Facility Topography: 10. Soil Type of local exposures: 11. Description of predominant surrounding vegetation type: 12. Description of nearby surface water: Name: NONE VISIBLE FROM SITE Distance: % slope: Type: Subtype: Size: 13. Drainage pathways visible? NO 14. Are surrounding lands jurisdictional wetlands? NO 15. Accessibility of the site for characterization and remediation, if requing the surrounding lands in the site for characterization and remediation, if requing lands is sellular telephone service available? 18. Is overnight shipper nearby? (i.e. Federal Express)						
	19. Are there any overhead obstructions that would affect remediation?	NO					
C. ADJACENT LAND USE	 20. Surrounding land use: Undeveloped 21. Approximate distance to nearby occupied structures (ft): 22. Evidence of public water services? NO 	Type of structure: NONE NEAR SITE					
D. EVIDENCE	23. Evidence of soil staining: NO						
OF A RELEASE	24. Surrounding vegetation stressed or discolored? NO						
FROM AN LRP OR ASSOCIATED	25. Evidence of release to nearby surface water? NO (e.g. oily sheen on top of surface water or along bank)						
FEATURES	26. Has a release to the ground occurred at this facility? NO POSSIBLY IN THE PAST, BUT NOT TO GUIDE'S KNOWLED	GE					
	27. Approximate size of impacted area (sq ft):						

	Facility ID: L05005
E. MMS EVIDENCE OF A RELEASE	28. Type of Meter Station: 29. Number of meters: 30. Describe the housing: 31. Flooring: 32. Number of doorways: 33. Evidence of mercury on soil surface? 34. Evidence of release in building? 35. MVA reading inside doorway: 36. Has a release to the ground occurred at this facility?
F. STORAGE WELL EVIDENCE OF A RELEASE	 37. Approximate size of impacted area (sq ft): 38. Evidence of soil staining? 39. Surrounding vegetation stressed or discolored? 40. Evidence of release to nearby surface water? 41. Evidence of discharge at wellhead annulus? 42. Nearby seeps with discharge and/or odor: 43. Approximate size of impacted area (sq ft):

Employee Name: Aaron Gaskins	RFW Facility ID: L05005
Date: 8/4/98 11:04:43	Columbia Facility Name, if any:
	Latitude:
	Longitude:
1. Removal point name: DRIP ON LINE J	10. Pipeline number: J
2. Township/city: BEDFORD	11. Associated well number: N/A
3. County: Coshocton	12a. Associated metering station number: N/A
4. State: Ohio	12b. Is this or was this a Mercury Metering Station?
5. Area: OHIO	13a. Inventory station number: 1149+93
	13b. Inventory map number: 4456-408
6. District: CENTRAL	14. Is the removal point on a backfed system? NO
7. Operating location: HOMER	15. How much liquid (gallons/year) has this removal point historically produced? 0 - 10
8. Removal point type: Liquid Removal Point	16. If the removal point produced liquids, how often were the liquids collected historically? Once/Year
9. Removal point function: TRANSMISSION	17. Approximately how many years has this removal point been in operation? >20
	18. Approximately how many years have fluids been produced? >20
	19. Is there knowledge of a release to the ground at this site? NO
	This release is associated with:
20a. How much liquid (gallons/year) has been released to the ground h	istorically? 0
20b. Historical discharge characteristics:	
NONE	
21. If the removal point produced liquids, how often were these liquid	s released to the ground historically? Never
22. If liquid releases have been identified in 19,20, or 21, what has been	en released?
23a. Has an historical, atypical release occurred at this site?	NO
23b. How much liquid (gallons) was released?	
23c. How many years ago was this release?	
24a. Are storage tanks associated with removal point?	o
24b. Number of years since tank installation?	
25. Other surface or subsurface features associated with removal poi	int:

RFW Facility ID: L05005		
26. Evidence of soil staining:	NO	
The staining is associated with:		
27. Evidence of stressed vegetation:	NO	
The evidence is associated with:		
28. Approximate size of release are		
29. Are there any nearby waterbodies:	NO	
Approximate distance to waterbody:		
30. (Reserved for Site Sketch.)		
31. (Reserved for LRP Photograph.)		
32. Site Access Restrictions:	Road Available; 4 WD Required	
Distance from main road:	100 ft. to 1/4 Mile	

Analytical Results Facility ID: L05005

			Analysis				Detection	
Field Sample ID	Matrix	Collected	Category	Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05005-SS001-40001	S	8/4/98	GC BTEX(S)	BENZENE	ND		5.9	UG/KG
L05005-SS001-40001	S	8/4/98	GC BTEX(S)	ETHYL BENZENE	ND		5.9	UG/KG
L05005-SS001-40001	S	8/4/98	GC BTEX(S)	TOLUENE	ND		5.9	UG/KG
L05005-SS001-40001	S	8/4/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.9	UG/KG
L05005-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1016	ND		39	UG/KG
L05005-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1221	ND		39	UG/KG
L05005-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1232	ND		39	UG/KG
L05005-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1242	ND		39	UG/KG
L05005-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1248	ND		39	UG/KG
L05005-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1254	ND		39	UG/KG
L05005-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1260	ND		39	UG/KG
L05005-SS002-40001	S	8/4/98	GC BTEX(S)	BENZENE	ND		6.0	UG/KG
L05005-SS002-40001	S	8/4/98	GC BTEX(S)	ETHYL BENZENE	ND		6.0	UG/KG
L05005-SS002-40001	S	8/4/98	GC BTEX(S)	TOLUENE	ND		6.0	UG/KG
L05005-SS002-40001	S	8/4/98	GC BTEX(S)	XYLENES (TOTAL)	ND		6.0	UG/KG
L05005-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1016	ND		39	UG/KG
L05005-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1221	ND		39	UG/KG
L05005-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1232	ND		39	UG/KG
L05005-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1242	ND		39	UG/KG
L05005-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1248	ND		39	UG/KG
L05005-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1254	ND		39	UG/KG
L05005-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1260	ND		39	UG/KG

^{*} Legend:

J=Estimated Analytical Value UJ=Estimated Detection Limit J+ =Estimated Analytical Value, Possible Biased High J- =Estimated Analytical Value, Possibly Biased Low

R=Rejected Result



Facility ID: L05005 Photo Date:08/04/98 12:04 HORIZONTAL DRIP ON LINE J AT STATION 1149+93



Facility ID: L05005 Photo Date:08/04/98 12:04 HORIZONTAL DRIP ON LINE J AT STATION 1149+93

Facility ID: L05005 Sketch 1 of 1 SAMPLE DATE: 8/4/98 SKETCHED BY: A. Gaskins WESTON FACILITY ID: L05005 COLUMBIA FACILITY ID/DESCRIPTION: Horizontal Drip on Line J Trees SS002 (P)-> \$5001 Line Tall Marker Plants -05005 HORIZONTAL DRIP End of horizontal drip to: \$5001-0" \$5002-4'3" Line marker to: \$5001 - 3' SSpo2-5'2" Tall trees at horizontal drip prevented a 3D fix there. To St. Rt. 60 ~ I mile X = measurement Decation SS001 (SAMPLE LOC.) **REMINDERS** YYYYY SLOPE MORTH ARROW ====== DIRT/GRAVEL RD TO ROAD NAMES SS001 ☐ ☆ GAS WELL PAVED ROAD SS002 OVERHEAD LINES A PHOTO DIRECTION - --- UNDRGD PIPELINE LINE MARKERS Υ EXPOSED PIPELINE ☐ OCCUPIED STRUCTURES **⊠** ⊕ GPS LOCATION SS001 APPROX. SCALE: 1 block = 1ft.? BUILDINGS SS002 ☐ SURFACE WATERS → DIRECTION OF FLOW

L05006

HORIZONTAL DRIP AT METER 720307 ON LINE J-54

SUMMARY OF FINDINGS AND RECOMMENDATIONS

This report has been prepared as part of the Active Screening Assessment (ASA), as defined under the Administrative Order on Consent for Removal Actions (AOC) issued to Columbia Gas Transmission Corporation (Columbia) by the U.S. Environmental Protection Agency (EPA), Docket No. III-94-35-DC. An ASAR is submitted to support the removal of facilities from the Work Scope List (WSL) when information and data collected pursuant to the Active Screening Assessment Work Plan (ASAWP) for Gathering Line Liquid Removal Points (LRPs) demonstrate that no further investigation or cleanup is warranted under the AOC.

This ASAR includes the Facility Conditions Survey, Liquid Removal Point Questionnaire (if any), analytical sampling results, facility sketch(es) and facility photograph(s) for facility L05006 in accordance with the ASAWP. Please note that the facility sketch may show facilities other than L05006 due to their close proximity to each other. This report is only for facility L05006. The sample locations are shown on the sketches and are visible as colored pin flags on the photograph(s).

All analytical sampling results for L05006 are below ASA Action Levels, as shown in Table 2 and defined in the ASAWP. State Action Levels for this facility are presented in Table 3 as defined by the Ohio Environmental Protection Agency. The documentation presented in this report demonstrates that Columbia characterized and performed a response action at facility L05006 pursuant to the ASAWP and that no further investigation or cleanup is warranted under the AOC for this facility. Therefore, Columbia requests that facility L05006 be removed from the WSL pursuant to Section 8.5(d) of the AOC.

Facility ID:	L05006 Facility Description:	HORIZONTAL DRIP AT METER 720307 ON LINE J-54						
Facility Type:	LRP Latitude: 40° 15' 48.8" N							
Survey Date:	8/4/98 Longitude: 82° 02' 31.5" W							
A. GENERAL INFO	Township/City: BEDFORD TOWNSHIP	5. District: CENTRAL						
	2. County: Coshocton	6. Operating Location: HOMER						
	3. State: Ohio	7. Pipeline Number: J-54						
	4. Area: OHIO	8. Well Number: N/A						
B. GENERAL FACILITY	9. Description of Facility Topography: Sloping (8 - 15 % slope)							
FEATURES	10. Soil Type of local exposures: Sandy I	oam						
	11. Description of predominant surrounding vegetation type: 12. Description of nearby surface water: Name: NONE VISIBLE FROM SITE Distance: % slope: Type: Subtype: Size:							
	13. Drainage pathways visible? NO							
	14. Are surrounding lands jurisdictional wetlands? NO							
	15. Accessibility of the site for characterization and remediation, if requi	red: Road available; however requires four-wheel drive vehicle						
	16. Nearest utilities less than 1/4 mile?	YES, OVERHEAD LINES						
	17. Is cellular telephone service available?	YES						
	18. Is overnight shipper nearby? (i.e. Federal Express)	YES						
	19. Are there any overhead obstructions that would affect remediation?	NO						
C. ADJACENT	20. Surrounding land use: Undeveloped							
LAND USE	21. Approximate distance to nearby occupied structures (ft): 20	Type of structure: HOUSE						
	22. Evidence of public water services? NO							
D. EVIDENCE	23. Evidence of soil staining: NO							
OF A RELEASE	24. Surrounding vegetation stressed or discolored? NO							
FROM AN LRP OR	25. Evidence of release to nearby surface water? NO (e.g. oily sheen on top of surface water or along bank)							
ASSOCIATED FEATURES	26. Has a release to the ground occurred at this facility? NO POSSIBLY IN THE PAST, BUT NOT TO GUIDE'S KNOWLEDGE							
	27. Approximate size of impacted area (sq ft):							

	Facility ID: L05006
E. MMS	28. Type of Meter Station:
EVIDENCE OF A	29. Number of meters:
RELEASE	30. Describe the housing:
	31. Flooring:
	32. Number of doorways:
	33. Evidence of mercury on soil surface?
	34. Evidence of release in building?
	35. MVA reading inside doorway:
	36. Has a release to the ground occurred at this facility?
	37. Approximate size of impacted area (sq ft):
F. STORAGE	38. Evidence of soil staining?
WELL EVIDENCE	39. Surrounding vegetation stressed or discolored?
OF A	40. Evidence of release to nearby surface water?
RELEASE	41. Evidence of discharge at wellhead annulus?
	42. Nearby seeps with discharge and/or odor:
	43. Approximate size of impacted area (sq ft):

Employee Name: Aaron Gaskins	RFW Facility ID: L05006			
Date: 8/4/98 13:48:42	Columbia Facility Name, if any:			
	Latitude: 40° 15' 48.8" N			
	Longitude: 82° 02' 31.5" W			
1 D 1 1 1 1 D D 1 1 1 1 2 2 2 2 2 2 2 2	10 B' I' 1 7 7 4			
1. Removal point name: DRIP AT METER 720307	10. Pipeline number: J-54			
2. Township/city: BEDFORD TOWNSHIP	11. Associated well number: N/A			
3. County: Coshocton	12a. Associated metering station number: 720307			
4. State: Ohio	12b. Is this or was this a Mercury Metering Station? NO			
5. Area: OHIO	13a. Inventory station number: N/A			
	13b. Inventory map number: 4456-408			
6. District: CENTRAL	14. Is the removal point on a backfed system? NO			
7. Operating location: HOMER	15. How much liquid (gallons/year) has this removal point historically produced? $\bf 0$ - $\bf 10$			
8. Removal point type: Liquid Removal Point	16. If the removal point produced liquids, how often were the liquids collected historically? Once/Year			
9. Removal point function: TRANSMISSION	17. Approximately how many years has this removal point been in operation? >20			
	18. Approximately how many years have fluids been produced? >20			
	19. Is there knowledge of a release to the ground at this site? NO			
	This release is associated with:			
20a. How much liquid (gallons/year) has been released to the ground historical	ly? 0			
20b. Historical discharge characteristics:				
NONE				
21. If the removal point produced liquids, how often were these liquids releas	ed to the ground historically? Never			
22. If liquid releases have been identified in 19,20, or 21, what has been relea				
23a. Has an historical, atypical release occurred at this site?				
23b. How much liquid (gallons) was released?				
23c. How many years ago was this release?				
24a. Are storage tanks associated with removal point? NO				
24b. Number of years since tank installation?				
2-to. Number of years since this installation:				
25. Other surface or subsurface features associated with removal point:				
1				
•				
•				

RFW Facility ID: L05006					
26. Evidence of soil staining:	NO				
The staining is associated with:					
27. Evidence of stressed vegetation:	NO				
The evidence is associated with:					
28. Approximate size of release are:	28. Approximate size of release are:				
29. Are there any nearby waterbodies:	NO				
Approximate distance to waterbody:					
30. (Reserved for Site Sketch.)					
31. (Reserved for LRP Photograph.)					
32. Site Access Restrictions:	Road Available; 4 WD Required				
Distance from main road:	Less Than 100 ft.				

Analytical Results Facility ID: L05006

			Analysis				Detection	
Field Sample ID	Matrix	Collected	Category	Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05006-SS001-40001	S	8/4/98	GC BTEX(S)	BENZENE	ND		6.0	UG/KG
L05006-SS001-40001	S	8/4/98	GC BTEX(S)	ETHYL BENZENE	ND		6.0	UG/KG
L05006-SS001-40001	S	8/4/98	GC BTEX(S)	TOLUENE	ND		6.0	UG/KG
L05006-SS001-40001	S	8/4/98	GC BTEX(S)	XYLENES (TOTAL)	ND		6.0	UG/KG
L05006-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1016	ND		39	UG/KG
L05006-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1221	ND		39	UG/KG
L05006-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1232	ND		39	UG/KG
L05006-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1242	ND		39	UG/KG
L05006-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1248	ND		39	UG/KG
L05006-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1254	ND		39	UG/KG
L05006-SS001-40001	S	8/4/98	PCB(S)	AROCLOR-1260	ND		39	UG/KG
L05006-SS002-40001	S	8/4/98	GC BTEX(S)	BENZENE	ND		5.7	UG/KG
L05006-SS002-40001	S	8/4/98	GC BTEX(S)	ETHYL BENZENE	ND		5.7	UG/KG
L05006-SS002-40001	S	8/4/98	GC BTEX(S)	TOLUENE	ND		5.7	UG/KG
L05006-SS002-40001	S	8/4/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.7	UG/KG
L05006-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1016	ND		38	UG/KG
L05006-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1221	ND		38	UG/KG
L05006-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1232	ND		38	UG/KG
L05006-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1242	ND		38	UG/KG
L05006-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1248	ND		38	UG/KG
L05006-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1254	ND		38	UG/KG
L05006-SS002-40001	S	8/4/98	PCB(S)	AROCLOR-1260	ND		38	UG/KG

^{*} Legend:

J=Estimated Analytical Value UJ=Estimated Detection Limit J+ =Estimated Analytical Value, Possible Biased High J- =Estimated Analytical Value, Possibly Biased Low

R=Rejected Result



Facility ID: L05006 Photo Date:08/04/98 14:27 HORIZONTAL DRIP AT METER 720307 ON LINE J-54



Facility ID: L05006 Photo Date:08/04/98 14:28 HORIZONTAL DRIP AT METER 720307 ON LINE J-54

L05007 HORIZONTAL DRIP ON LINE J-54 AT STATION 194+64

SUMMARY OF FINDINGS AND RECOMMENDATIONS

This report has been prepared as part of the Active Screening Assessment (ASA), as defined under the Administrative Order on Consent for Removal Actions (AOC) issued to Columbia Gas Transmission Corporation (Columbia) by the U.S. Environmental Protection Agency (EPA), Docket No. III-94-35-DC. An ASAR is submitted to support the removal of facilities from the Work Scope List (WSL) when information and data collected pursuant to the Active Screening Assessment Work Plan (ASAWP) for Gathering Line Liquid Removal Points (LRPs) demonstrate that no further investigation or cleanup is warranted under the AOC.

This ASAR includes the Facility Conditions Survey, Liquid Removal Point Questionnaire (if any), analytical sampling results, facility sketch(es) and facility photograph(s) for facility L05007 in accordance with the ASAWP. Please note that the facility sketch may show facilities other than L05007 due to their close proximity to each other. This report is only for facility L05007. The sample locations are shown on the sketches and are visible as colored pin flags on the photograph(s).

All analytical sampling results for L05007 are below ASA Action Levels, as shown in Table 2 and defined in the ASAWP. State Action Levels for this facility are presented in Table 3 as defined by the Ohio Environmental Protection Agency. The documentation presented in this report demonstrates that Columbia characterized and performed a response action at facility L05007 pursuant to the ASAWP and that no further investigation or cleanup is warranted under the AOC for this facility. Therefore, Columbia requests that facility L05007 be removed from the WSL pursuant to Section 8.5(d) of the AOC.

Facility ID:	L05007 Facility Description: I	IORIZONTAL DRIP ON LINE J-54 AT STATION 194+64
Facility Type:	LRP Latitude:	
Survey Date:	8/5/98 Longitude:	
A. GENERAL INFO	 Township/City: JEFFERSON TOWNSHIP County: Coshocton State: Ohio Area: OHIO 	5. District: CENTRAL 6. Operating Location: HOMER 7. Pipeline Number: J-54 8. Well Number: N/A
B. GENERAL FACILITY FEATURES	9. Description of Facility Topography: 10. Soil Type of local exposures: 11. Description of predominant surrounding vegetation type: 12. Description of nearby surface water: Name: NONE VISIBLE FROM SITE Distance: % slope: Type: Subtype: Size: 13. Drainage pathways visible? NO 14. Are surrounding lands jurisdictional wetlands? NO 15. Accessibility of the site for characterization and remediation, if requi	Teed: Road available; however requires four-wheel drive vehicle YES NO YES
C. ADJACENT LAND USE	 19. Are there any overhead obstructions that would affect remediation? 20. Surrounding land use: Undeveloped 21. Approximate distance to nearby occupied structures (ft): 25 22. Evidence of public water services? NO 	NO Type of structure: HOUSE
D. EVIDENCE OF A RELEASE FROM AN LRP OR ASSOCIATED FEATURES	 23. Evidence of soil staining: NO 24. Surrounding vegetation stressed or discolored? NO 25. Evidence of release to nearby surface water? NO (e.g. oily sheen on top of surface water or along bank) 26. Has a release to the ground occurred at this facility? NO POSSIBLY IN THE PAST, BUT NOT TO GUIDE'S KNOWLED 27. Approximate size of impacted area (sq ft): 	GE

	Facility ID: L05007
E. MMS	28. Type of Meter Station:
EVIDENCE OF A	29. Number of meters:
RELEASE	30. Describe the housing:
	31. Flooring:
	32. Number of doorways:
	33. Evidence of mercury on soil surface?
	34. Evidence of release in building?
	35. MVA reading inside doorway:
	36. Has a release to the ground occurred at this facility?
	37. Approximate size of impacted area (sq ft):
F. STORAGE	38. Evidence of soil staining?
WELL EVIDENCE	39. Surrounding vegetation stressed or discolored?
OF A	40. Evidence of release to nearby surface water?
RELEASE	41. Evidence of discharge at wellhead annulus?
	42. Nearby seeps with discharge and/or odor:
	43. Approximate size of impacted area (sq ft):

RFW Facility ID: L05007						
Columbia Facility Name, if any:						
Latitude:						
Longitude:						
10. Pipeline number: J-54						
11. Associated well number: N/A						
12a. Associated metering station number: N/A						
12b. Is this or was this a Mercury Metering Station?						
13a. Inventory station number: 194+64						
13b. Inventory map number: 4460-412						
14. Is the removal point on a backfed system? NO						
15. How much liquid (gallons/year) has this removal point historically produced? 0 - 10						
16. If the removal point produced liquids, how often were the liquids collected historically? Once/Year						
17. Approximately how many years has this removal point been in operation? >20						
18. Approximately how many years have fluids been produced? >20						
19. Is there knowledge of a release to the ground at this site?						
This release is associated with:						
ally? 0						
sed to the ground historically? Never						
ased?						
0						
23c. How many years ago was this release?						
24a. Are storage tanks associated with removal point? NO						
24b. Number of years since tank installation?						

RFW Facility ID: L05007	
26. Evidence of soil staining:	NO
The staining is associated with:	
27. Evidence of stressed vegetation:	NO
The evidence is associated with:	
28. Approximate size of release are:	
29. Are there any nearby waterbodies:	NO
Approximate distance to waterbody:	
30. (Reserved for Site Sketch.)	
31. (Reserved for LRP Photograph.)	
32. Site Access Restrictions:	Road Available; 4 WD Required
Distance from main road:	Less Than 100 ft.

Analytical Results Facility ID: L05007

S S S S S S S S S S S S S S S S S S S	8/5/98 8/5/98 8/5/98 8/5/98 8/5/98	GC BTEX(S) GC BTEX(S) GC BTEX(S) GC BTEX(S) GC BTEX(S)	Parameter BENZENE ETHYL BENZENE TOLUENE	Result ND ND	Flag*	6.2	Units UG/KG
S S S S	8/5/98 8/5/98 8/5/98 8/5/98	GC BTEX(S) GC BTEX(S)	ETHYL BENZENE	ND			UG/KG
S S S S	8/5/98 8/5/98 8/5/98 8/5/98	GC BTEX(S) GC BTEX(S)	ETHYL BENZENE	ND			UG/KC
S S S	8/5/98 8/5/98 8/5/98	GC BTEX(S)				<i>c</i> 2	
S S S	8/5/98 8/5/98	• •	TOLUENE			6.2	UG/KC
S S	8/5/98	GC BTEX(S)		ND		6.2	UG/KC
S			XYLENES (TOTAL)	ND		6.2	UG/KC
	0.17.10.0	PCB(S)	AROCLOR-1016	ND		41	UG/KC
S	8/5/98	PCB(S)	AROCLOR-1221	ND		41	UG/KC
	8/5/98	PCB(S)	AROCLOR-1232	ND		41	UG/KC
S	8/5/98	PCB(S)	AROCLOR-1242	ND		41	UG/KC
S	8/5/98	PCB(S)	AROCLOR-1248	ND		41	UG/KC
S	8/5/98	PCB(S)	AROCLOR-1254	ND		41	UG/KC
S	8/5/98	PCB(S)	AROCLOR-1260	ND		41	UG/KC
S	8/5/98	GC BTEX(S)	BENZENE	ND		5.9	UG/KC
S	8/5/98	GC BTEX(S)	ETHYL BENZENE	ND		5.9	UG/KC
S	8/5/98	GC BTEX(S)	TOLUENE	ND		5.9	UG/KC
S	8/5/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.9	UG/KC
S	8/5/98	PCB(S)	AROCLOR-1016	ND		39	UG/KC
S	8/5/98	PCB(S)	AROCLOR-1221	ND		39	UG/KC
S	8/5/98	PCB(S)	AROCLOR-1232	ND		39	UG/KC
S	8/5/98	PCB(S)	AROCLOR-1242	ND		39	UG/KC
S	8/5/98	PCB(S)	AROCLOR-1248	ND		39	UG/KC
S	8/5/98	PCB(S)	AROCLOR-1254	ND		39	UG/KC
S	8/5/98	PCB(S)	AROCLOR-1260	ND		39	UG/KC
	S S S S S S S S S S S S S S S S S S S	S 8/5/98	S 8/5/98 PCB(S) S 8/5/98 GC BTEX(S) S 8/5/98 GC BTEX(S) S 8/5/98 GC BTEX(S) S 8/5/98 PCB(S)	S 8/5/98 PCB(S) AROCLOR-1242 S 8/5/98 PCB(S) AROCLOR-1248 S 8/5/98 PCB(S) AROCLOR-1254 S 8/5/98 PCB(S) AROCLOR-1260 S 8/5/98 PCB(S) BENZENE S 8/5/98 GC BTEX(S) ETHYL BENZENE S 8/5/98 GC BTEX(S) TOLUENE S 8/5/98 PCB(S) AROCLOR-1016 S 8/5/98 PCB(S) AROCLOR-1221 S 8/5/98 PCB(S) AROCLOR-1232 S 8/5/98 PCB(S) AROCLOR-1242 S 8/5/98 PCB(S) AROCLOR-1248 S 8/5/98 PCB(S) AROCLOR-1254	S 8/5/98 PCB(S) AROCLOR-1242 ND S 8/5/98 PCB(S) AROCLOR-1248 ND S 8/5/98 PCB(S) AROCLOR-1254 ND S 8/5/98 PCB(S) AROCLOR-1260 ND S 8/5/98 PCB(S) AROCLOR-1260 ND S 8/5/98 GC BTEX(S) ETHYL BENZENE ND S 8/5/98 GC BTEX(S) TOLUENE ND S 8/5/98 GC BTEX(S) XYLENES (TOTAL) ND S 8/5/98 PCB(S) AROCLOR-1016 ND S 8/5/98 PCB(S) AROCLOR-1221 ND S 8/5/98 PCB(S) AROCLOR-1232 ND S 8/5/98 PCB(S) AROCLOR-1242 ND S 8/5/98 PCB(S) AROCLOR-1248 ND S 8/5/98 PCB(S) AROCLOR-1254 ND	S 8/5/98 PCB(S) AROCLOR-1242 ND S 8/5/98 PCB(S) AROCLOR-1248 ND S 8/5/98 PCB(S) AROCLOR-1254 ND S 8/5/98 PCB(S) AROCLOR-1260 ND S 8/5/98 PCB(S) BENZENE ND S 8/5/98 GC BTEX(S) ETHYL BENZENE ND S 8/5/98 GC BTEX(S) TOLUENE ND S 8/5/98 GC BTEX(S) XYLENES (TOTAL) ND S 8/5/98 PCB(S) AROCLOR-1016 ND S 8/5/98 PCB(S) AROCLOR-1221 ND S 8/5/98 PCB(S) AROCLOR-1232 ND S 8/5/98 PCB(S) AROCLOR-1242 ND S 8/5/98 PCB(S) AROCLOR-1248 ND S 8/5/98 PCB(S) AROCLOR-1254 ND	S 8/5/98 PCB(S) AROCLOR-1242 ND 41 S 8/5/98 PCB(S) AROCLOR-1248 ND 41 S 8/5/98 PCB(S) AROCLOR-1254 ND 41 S 8/5/98 PCB(S) AROCLOR-1260 ND 41 S 8/5/98 PCB(S) BENZENE ND 5.9 S 8/5/98 GC BTEX(S) ETHYL BENZENE ND 5.9 S 8/5/98 GC BTEX(S) TOLUENE ND 5.9 S 8/5/98 GC BTEX(S) XYLENES (TOTAL) ND 5.9 S 8/5/98 PCB(S) AROCLOR-1016 ND 39 S 8/5/98 PCB(S) AROCLOR-1221 ND 39 S 8/5/98 PCB(S) AROCLOR-1232 ND 39 S 8/5/98 PCB(S) AROCLOR-1242 ND 39 S 8/5/98 PCB(S) AROCLOR-1248 ND 39 S 8/5/98 PCB(S) AROCLOR-1254 ND 39

Analytical Results Facility ID: L05007

			Analysis				Detection	
Field Sample ID	Matrix	Collected	Category	Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05007-SS002-40001	S	8/5/98	GC BTEX(S)	BENZENE	ND		5.8	UG/KG
L05007-SS002-40001	S	8/5/98	GC BTEX(S)	ETHYL BENZENE	ND		5.8	UG/KG
L05007-SS002-40001	S	8/5/98	GC BTEX(S)	TOLUENE	ND		5.8	UG/KG
L05007-SS002-40001	S	8/5/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.8	UG/KG
L05007-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1016	ND		38	UG/KG
L05007-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1221	ND		38	UG/KG
L05007-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1232	ND		38	UG/KG
L05007-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1242	ND		38	UG/KG
L05007-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1248	ND		38	UG/KG
L05007-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1254	ND		38	UG/KG
L05007-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1260	ND		38	UG/KG

^{*} Legend:

J=Estimated Analytical Value UJ=Estimated Detection Limit

J+ =Estimated Analytical Value, Possible Biased High J- =Estimated Analytical Value, Possibly Biased Low

R=Rejected Result



Facility ID: L05007 Photo Date:08/05/98 10:31 HORIZONTAL DRIP ON LINE J-54 AT STATION 194+64

Facility ID: L05007 Sketch 1 of 1 SKETCHED BY: A. Gaskins WESTON FACILITY ID: L 05007 SAMPLE DATE: 8/5/98 C COLUMBIA FACILITY ID/DESCRIPTION: Horizontal Drip on Line J-54 Rotary Meter ~5' I Ŋ 0 Z 55002 ***•** \$500 I L05007 HORIZONTAL (P2) (PI) DRIP × Flat Line Marker End of Horizontal 1 Drip to: Tall 5\$001 - 0" S\$002 -5'4" Plants Flat Line Marker to! S5001-2'5" \$\$00, \$\$002 - 7' Tefferson Township Road 55A House ~200 X = measurement

S = SS001 (SAMPLE LOC.) REMINDERS YYYYY SLOPE Υ Х **I** NORTH ARROW ==== DIRT/GRAVEL RD SS001 ROAD NAMES 76 ☐ ☆ GAS WELL PAVED ROAD SS002] OVERHEAD LINES A PHOTO DIRECTION - -- UNDRGD PIPELINE Х Υ LINE MARKERS EXPOSED PIPELINE 1 OCCUPIED STRUCTURES SS001 ☑ ⊕ GPS LOCATION BUILDINGS & APPROX. SCALE: | block = 1 ft.2 SS002) SURFACE WATERS DIRECTION OF FLOW

THE MILLION THE WILLIAM THE

L05008

HORIZONTAL DRIP ON LINE J-54 AT STATION 297+15

SUMMARY OF FINDINGS AND RECOMMENDATIONS

This report has been prepared as part of the Active Screening Assessment (ASA), as defined under the Administrative Order on Consent for Removal Actions (AOC) issued to Columbia Gas Transmission Corporation (Columbia) by the U.S. Environmental Protection Agency (EPA), Docket No. III-94-35-DC. An ASAR is submitted to support the removal of facilities from the Work Scope List (WSL) when information and data collected pursuant to the Active Screening Assessment Work Plan (ASAWP) for Gathering Line Liquid Removal Points (LRPs) demonstrate that no further investigation or cleanup is warranted under the AOC.

This ASAR includes the Facility Conditions Survey, Liquid Removal Point Questionnaire (if any), analytical sampling results, facility sketch(es) and facility photograph(s) for facility L05008 in accordance with the ASAWP. Please note that the facility sketch may show facilities other than L05008 due to their close proximity to each other. This report is only for facility L05008. The sample locations are shown on the sketches and are visible as colored pin flags on the photograph(s).

All analytical sampling results for L05008 are below ASA Action Levels, as shown in Table 2 and defined in the ASAWP. State Action Levels for this facility are presented in Table 3 as defined by the Ohio Environmental Protection Agency. The documentation presented in this report demonstrates that Columbia characterized and performed a response action at facility L05008 pursuant to the ASAWP and that no further investigation or cleanup is warranted under the AOC for this facility. Therefore, Columbia requests that facility L05008 be removed from the WSL pursuant to Section 8.5(d) of the AOC.

Facility ID:	L05008 Facility Description: H	ORIZONTAL DRIP ON LINE J-54 AT STATION 297+15
Facility Type:	LRP Latitude: 40° 19' 54.0" N	
Survey Date:	8/5/98 Longitude: 82° 00' 37.7" W	
A. GENERAL INFO	 Township/City: JEFFERSON TOWNSHIP County: Coshocton State: Ohio Area: OHIO 	5. District: CENTRAL 6. Operating Location: HOMER 7. Pipeline Number: J-54 8. Well Number: N/A
B. GENERAL FACILITY FEATURES	9. Description of Facility Topography: 10. Soil Type of local exposures: 11. Description of predominant surrounding vegetation type: 12. Description of nearby surface water: Name: NONE VISIBLE FROM SITE Distance: % slope: Type: Subtype: Size: 13. Drainage pathways visible? NO 14. Are surrounding lands jurisdictional wetlands? NO 15. Accessibility of the site for characterization and remediation, if required. Nearest utilities less than 1/4 mile? 16. Nearest utilities less than 1/4 mile? 17. Is cellular telephone service available? 18. Is overnight shipper nearby? (i.e. Federal Express) 19. Are there any overhead obstructions that would affect remediation?	ed: Road all the way to site YES YES YES NO
C. ADJACENT LAND USE	20. Surrounding land use: Agricultural 21. Approximate distance to nearby occupied structures (ft): 200 22. Evidence of public water services? NO	
D. EVIDENCE OF A RELEASE FROM AN LRP OR ASSOCIATED FEATURES	 23. Evidence of soil staining: NO 24. Surrounding vegetation stressed or discolored? NO 25. Evidence of release to nearby surface water? NO (e.g. oily sheen on top of surface water or along bank) 26. Has a release to the ground occurred at this facility? NO POSSIBLY IN THE PAST, BUT NOT TO GUIDE'S KNOWLEDGE 27. Approximate size of impacted area (sq ft): 	GE

	Facility ID: L05008
E. MMS EVIDENCE OF A RELEASE	28. Type of Meter Station: 29. Number of meters: 30. Describe the housing: 31. Flooring: 32. Number of doorways: 33. Evidence of mercury on soil surface? 34. Evidence of release in building? 35. MVA reading inside doorway: 36. Has a release to the ground occurred at this facility? 37. Approximate size of impacted area (sq ft):
F. STORAGE WELL EVIDENCE OF A RELEASE	38. Evidence of soil staining? 39. Surrounding vegetation stressed or discolored? 40. Evidence of release to nearby surface water? 41. Evidence of discharge at wellhead annulus? 42. Nearby seeps with discharge and/or odor: 43. Approximate size of impacted area (sq ft):

Employee Name: Josh Mannke	RFW Facility ID: L05008				
Date: 8/5/98 11:40:18	Columbia Facility Name, if any:				
	Latitude: 40° 19' 54.0" N				
	Longitude: 82° 00' 37.7" W				
1. Removal point name: DRIP ON LINE J-54	10. Pipeline number: J-54				
2. Township/city: JEFFERSON TOWNSHIP	11. Associated well number: N/A				
3. County: Coshocton	12a. Associated metering station number: N/A				
4. State: Ohio	12b. Is this or was this a Mercury Metering Station?				
5. Area: OHIO	13a. Inventory station number: 194+64				
	13b. Inventory map number: 4464-412				
6. District: CENTRAL	14. Is the removal point on a backfed system? NO				
7. Operating location: HOMER	15. How much liquid (gallons/year) has this removal point historically produced? 0 - 10				
8. Removal point type: Liquid Removal Point	16. If the removal point produced liquids, how often were the liquids collected historically? Once/Year				
9. Removal point function: TRANSMISSION	17. Approximately how many years has this removal point been in operation? >20				
	18. Approximately how many years have fluids been produced? >20				
	19. Is there knowledge of a release to the ground at this site?				
	This release is associated with:				
20a. How much liquid (gallons/year) has been released to the ground historical	lly? 0				
20b. Historical discharge characteristics:					
NONE					
21. If the removal point produced liquids, how often were these liquids releas	ed to the ground historically? Never				
22. If liquid releases have been identified in 19,20, or 21, what has been relea	sed?				
23a. Has an historical, atypical release occurred at this site?					
23b. How much liquid (gallons) was released?					
23c. How many years ago was this release?					
24a. Are storage tanks associated with removal point? NO					
24b. Number of years since tank installation?					
25. Other surface or subsurface features associated with removal point:					

RFW Facility ID: L05008	
26. Evidence of soil staining:	NO
The staining is associated with:	
27. Evidence of stressed vegetation:	NO
The evidence is associated with:	
28. Approximate size of release are:	
29. Are there any nearby waterbodies:	NO NO
Approximate distance to waterbody:	
30. (Reserved for Site Sketch.)	
31. (Reserved for LRP Photograph.)	
32. Site Access Restrictions:	Road All The Way To Site
Distance from main road:	Less Than 100 ft.

Analytical Results Facility ID: L05008

			Analysis				Detection	
Field Sample ID	Matrix	Collected	Category	Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05008-SS001-40001	S	8/5/98	GC BTEX(S)	BENZENE	ND		6.0	UG/KG
L05008-SS001-40001	S	8/5/98	GC BTEX(S)	ETHYL BENZENE	ND		6.0	UG/KG
L05008-SS001-40001	S	8/5/98	GC BTEX(S)	TOLUENE	ND		6.0	UG/KG
L05008-SS001-40001	S	8/5/98	GC BTEX(S)	XYLENES (TOTAL)	ND		6.0	UG/KG
L05008-SS001-40001	S	8/5/98	PCB(S)	AROCLOR-1016	ND		40	UG/KG
L05008-SS001-40001	S	8/5/98	PCB(S)	AROCLOR-1221	ND		40	UG/KG
L05008-SS001-40001	S	8/5/98	PCB(S)	AROCLOR-1232	ND		40	UG/KG
L05008-SS001-40001	S	8/5/98	PCB(S)	AROCLOR-1242	ND		40	UG/KG
L05008-SS001-40001	S	8/5/98	PCB(S)	AROCLOR-1248	ND		40	UG/KG
L05008-SS001-40001	S	8/5/98	PCB(S)	AROCLOR-1254	ND		40	UG/KG
L05008-SS001-40001	S	8/5/98	PCB(S)	AROCLOR-1260	ND		40	UG/KG
L05008-SS002-40001	S	8/5/98	GC BTEX(S)	BENZENE	ND		5.9	UG/KG
L05008-SS002-40001	S	8/5/98	GC BTEX(S)	ETHYL BENZENE	ND		5.9	UG/KG
L05008-SS002-40001	S	8/5/98	GC BTEX(S)	TOLUENE	ND		5.9	UG/KG
L05008-SS002-40001	S	8/5/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.9	UG/KG
L05008-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1016	ND		39	UG/KG
L05008-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1221	ND		39	UG/KG
L05008-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1232	ND		39	UG/KG
L05008-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1242	ND		39	UG/KG
L05008-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1248	ND		39	UG/KG
L05008-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1254	ND		39	UG/KG
L05008-SS002-40001	S	8/5/98	PCB(S)	AROCLOR-1260	ND		39	UG/KG
L								

^{*} Legend:

J=Estimated Analytical Value UJ=Estimated Detection Limit J+ =Estimated Analytical Value, Possible Biased High J- =Estimated Analytical Value, Possibly Biased Low

R=Rejected Result



Facility ID: L05008 Photo Date:08/05/98 12:08 HORIZONTAL DRIP ON LINE J-54 AT STATION 297+15



Facility ID: L05008 Photo Date:08/05/98 12:08 HORIZONTAL DRIP ON LINE J-54 AT STATION 297+15

Facility ID: L05008 Sketch 1 of 1_ WESTON FACILITY ID: LOSCO SKETCHED BY: 5. WMN N SAMPLE DATER & . CA C COLUMBIA FACILITY IDIDESCRIPTION: Horizonto / Deig 30 1:0 534 NETTO -X.5000/ Hos: 25.70 Fence Fonce 0 REMINDERS YYYYY SLOPE MORTH ARROW ☐ SS001 (SAMPLE LOC.) __ _ _ _ _ DIRT/GRAVEL RD DGL SS001 ROAD NAMES ☐ \$ GAS WELL PAVED ROAD SS002 1 OVERHEAD LINES PHOTO DIRECTION UNDRGD PIPELINE LINE MARKERS --- EXPOSED PIPELINE OCCUPIED STRUCTURES GPS LOCATION SS001 BUILDINGS ☐ APPROX. SCALE: SS002 SURFACE WATERS DIRECTION OF FLOW

L05009

DISPLACEMENT METER 731230 ON LINE Q-930

SUMMARY OF FINDINGS AND RECOMMENDATIONS

This report has been prepared as part of the Active Screening Assessment (ASA), as defined under the Administrative Order on Consent for Removal Actions (AOC) issued to Columbia Gas Transmission Corporation (Columbia) by the U.S. Environmental Protection Agency (EPA), Docket No. III-94-35-DC. An ASAR is submitted to support the removal of facilities from the Work Scope List (WSL) when information and data collected pursuant to the Active Screening Assessment Work Plan (ASAWP) for Gathering Line Liquid Removal Points (LRPs) demonstrate that no further investigation or cleanup is warranted under the AOC.

This ASAR includes the Facility Conditions Survey, Liquid Removal Point Questionnaire (if any), analytical sampling results, facility sketch(es) and facility photograph(s) for facility L05009 in accordance with the ASAWP. Please note that the facility sketch may show facilities other than L05009 due to their close proximity to each other. This report is only for facility L05009. The sample locations are shown on the sketches and are visible as colored pin flags on the photograph(s).

All analytical sampling results for L05009 are below ASA Action Levels, as shown in Table 2 and defined in the ASAWP. State Action Levels for this facility are presented in Table 3 as defined by the Ohio Environmental Protection Agency. The documentation presented in this report demonstrates that Columbia characterized and performed a response action at facility L05009 pursuant to the ASAWP and that no further investigation or cleanup is warranted under the AOC for this facility. Therefore, Columbia requests that facility L05009 be removed from the WSL pursuant to Section 8.5(d) of the AOC.

Facility ID:	L05009 Facility Description: D	ISPLACEMENT METER 731230 ON LINE Q-930			
Facility Type:	LRP Latitude: 39° 19' 13.5" N				
Survey Date:	8/6/98 Longitude: 81° 48' 09.9" W				
A. GENERAL	1. Township/City: DECATUR TOWNSHIP	5. District: SOUTHERN			
INFO	2. County: Washington	6. Operating Location: ATHENS			
	3. State: Ohio	7. Pipeline Number: Q-930			
	4. Area: OHIO	8. Well Number: N/A			
B. GENERAL	9. Description of Facility Topography: Strongly	Sloping (15 - 25% slope)			
FACILITY FEATURES	10. Soil Type of local exposures: Sandy C	lay Loam			
LITTORES	11. Description of predominant surrounding vegetation type: Shrub				
	12. Description of nearby surface water: Name: NONE VISIBLE FROM SITE Distance: % slope: Type: Subtype: Size:				
	13. Drainage pathways visible? NO				
	14. Are surrounding lands jurisdictional wetlands? NO				
	15. Accessibility of the site for characterization and remediation, if require	ed: Road all the way to site			
	16. Nearest utilities less than 1/4 mile?	NO			
	17. Is cellular telephone service available?	YES			
	18. Is overnight shipper nearby? (i.e. Federal Express)	YES			
	19. Are there any overhead obstructions that would affect remediation?	NO			
C. ADJACENT	20. Surrounding land use: Undeveloped				
LAND USE	21. Approximate distance to nearby occupied structures (ft):	Type of structure: NONE SEAR SITE			
	22. Evidence of public water services? NO				
D. EVIDENCE	23. Evidence of soil staining: NO				
OF A RELEASE	24. Surrounding vegetation stressed or discolored? NO				
FROM AN LRP OR	25. Evidence of release to nearby surface water? NO (e.g. oily sheen on top of surface water or along bank)				
ASSOCIATED FEATURES	26. Has a release to the ground occurred at this facility? NO POSSIBLY IN THE PAST, BUT NOT TO GUIDE'S KNOWLEDGE	FE .			
	27. Approximate size of impacted area (sq ft):				

	Facility ID: L05009
E. MMS	28. Type of Meter Station:
EVIDENCE OF A	29. Number of meters:
RELEASE	30. Describe the housing:
	31. Flooring:
	32. Number of doorways:
	33. Evidence of mercury on soil surface?
	34. Evidence of release in building?
	35. MVA reading inside doorway:
	36. Has a release to the ground occurred at this facility?
	37. Approximate size of impacted area (sq ft):
F. STORAGE	38. Evidence of soil staining?
WELL EVIDENCE	39. Surrounding vegetation stressed or discolored?
OF A	40. Evidence of release to nearby surface water?
RELEASE	41. Evidence of discharge at wellhead annulus?
	42. Nearby seeps with discharge and/or odor:
	43. Approximate size of impacted area (sq ft):

RFW Facility ID: L05009					
Columbia Facility Name, if any: 731230					
Latitude: 39° 19' 13.5" N					
Longitude: 81° 48' 09.9" W					
10. Pipeline number: Q-930					
11. Associated well number: N/A					
12a. Associated metering station number: 731230					
12b. Is this or was this a Mercury Metering Station?					
13a. Inventory station number: N/A					
13b. Inventory map number: 4352-428					
14. Is the removal point on a backfed system? NO					
15. How much liquid (gallons/year) has this removal point historically produced? 0 - 10					
16. If the removal point produced liquids, how often were the liquids collected historically? Once/Year					
17. Approximately how many years has this removal point been in operation? >10					
18. Approximately how many years have fluids been produced? >10					
19. Is there knowledge of a release to the ground at this site?					
This release is associated with:					
lly? 0					
ed to the ground historically? Never					
22. If liquid releases have been identified in 19,20, or 21, what has been released?					
23b. How much liquid (gallons) was released?					
23c. How many years ago was this release?					
24a. Are storage tanks associated with removal point? NO					
24b. Number of years since tank installation?					
25. Other surface or subsurface features associated with removal point:					

RFW Facility ID: L05009					
26. Evidence of soil staining:	NO				
The staining is associated with:					
27. Evidence of stressed vegetation:	NO				
The evidence is associated with:					
28. Approximate size of release are:					
29. Are there any nearby waterbodies:	NO				
Approximate distance to waterbody:					
30. (Reserved for Site Sketch.)					
31. (Reserved for LRP Photograph.)					
32. Site Access Restrictions:	Road All The Way To Site				
Distance from main road:	Less Than 100 ft.				

Analytical Results Facility ID: L05009

			Analysis				Detection	
Field Sample ID	Matrix	Collected		Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05009-SS001-40001	S	8/6/98	GC BTEX(S)	BENZENE	ND		5.7	UG/KC
L05009-SS001-40001	S	8/6/98	GC BTEX(S)	ETHYL BENZENE	ND		5.7	UG/KC
L05009-SS001-40001	S	8/6/98	GC BTEX(S)	TOLUENE	ND		5.7	UG/KC
L05009-SS001-40001	S	8/6/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.7	UG/KC
L05009-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1016	ND		38	UG/KC
L05009-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1221	ND		38	UG/KC
L05009-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1232	ND		38	UG/KC
L05009-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1242	ND		38	UG/KC
L05009-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1248	ND		38	UG/KC
L05009-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1254	ND		38	UG/KC
L05009-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1260	ND		38	UG/KO
L05009-SS001-41001 (Field Dup)	S	8/6/98	GC BTEX(S)	BENZENE	ND		6.0	UG/KC
L05009-SS001-41001 (Field Dup)	S	8/6/98	GC BTEX(S)	ETHYL BENZENE	ND		6.0	UG/KC
L05009-SS001-41001 (Field Dup)	S	8/6/98	GC BTEX(S)	TOLUENE	ND		6.0	UG/KC
L05009-SS001-41001 (Field Dup)	S	8/6/98	GC BTEX(S)	XYLENES (TOTAL)	ND		6.0	UG/KC
L05009-SS001-41001 (Field Dup)	S	8/6/98	PCB(S)	AROCLOR-1016	ND		39	UG/KC
L05009-SS001-41001 (Field Dup)	S	8/6/98	PCB(S)	AROCLOR-1221	ND		39	UG/KC
L05009-SS001-41001 (Field Dup)	S	8/6/98	PCB(S)	AROCLOR-1232	ND		39	UG/KC
L05009-SS001-41001 (Field Dup)	S	8/6/98	PCB(S)	AROCLOR-1242	ND		39	UG/KC
L05009-SS001-41001 (Field Dup)	S	8/6/98	PCB(S)	AROCLOR-1248	ND		39	UG/K0
L05009-SS001-41001 (Field Dup)	S	8/6/98	PCB(S)	AROCLOR-1254	ND		39	UG/K0
L05009-SS001-41001 (Field Dup)	S	8/6/98	PCB(S)	AROCLOR-1260	ND		39	UG/KC

Analytical Results Facility ID: L05009

			Analysis				Detection	
Field Sample ID	Matrix	Collected	Category	Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05009-SS002-40001	S	8/6/98	GC BTEX(S)	BENZENE	ND		5.8	UG/KG
L05009-SS002-40001	S	8/6/98	GC BTEX(S)	ETHYL BENZENE	ND		5.8	UG/KG
L05009-SS002-40001	S	8/6/98	GC BTEX(S)	TOLUENE	ND		5.8	UG/KG
L05009-SS002-40001	S	8/6/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.8	UG/KG
L05009-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1016	ND		38	UG/KG
L05009-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1221	ND		38	UG/KG
L05009-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1232	ND		38	UG/KG
L05009-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1242	ND		38	UG/KG
L05009-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1248	ND		38	UG/KG
L05009-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1254	ND		38	UG/KG
L05009-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1260	ND		38	UG/KG

^{*} Legend:

J=Estimated Analytical Value UJ=Estimated Detection Limit

J+ =Estimated Analytical Value, Possible Biased High J- =Estimated Analytical Value, Possibly Biased Low

R=Rejected Result



Facility ID: L05009 Photo Date:08/06/98 10:26 DISPLACEMENT METER 731230 ON LINE Q-930



Facility ID: L05009 Photo Date:08/06/98 10:27 DISPLACEMENT METER 731230 ON LINE Q-930

Facility ID: L05009 Sketch 1 of 1 SAMPLE DATE: 8/6/98 SKETCHED BY: A. Gaskins VESTON FACILITY ID: L 05009 C COLUMBIA FACILITY IDIDESCRIPTION: Displacement Meter 731230 on Line Q-930 0 55001 A L05009 55002 DISPLACEMENT METER NORTH (P2) ← Call plants → Top of displacement meter to: 55001-1/4" oLine Marker SS002-7'8" ø End of pipe to: SS001-212" SS002 - 3'11" S Decatur Township Road X = measurement location SS001 (SAMPLE LOC.) TYYYY SLOPE Y REMINDERS Х) NORTH ARROW __ _ _ _ DIRT/GRAVEL RD SS001 I ROAD NAMES (☐ ☆ GAS WELL __ PAVED ROAD SS002) OVERHEAD LINES M PHOTO DIRECTION - --- UNDRGD PIPELINE Y X) LINE MARKERS EXPOSED PIPELINE) OCCUPIED STRUCTURES **⊠** ⊕ GPS LOCATION SS001 BUILDINGS APPROX. SCALE: I block \$\$002 I SURFACE WATERS DIRECTION OF FLOW

L05010

DISPLACEMENT METER 732042 ON LINE Q-926

SUMMARY OF FINDINGS AND RECOMMENDATIONS

This report has been prepared as part of the Active Screening Assessment (ASA), as defined under the Administrative Order on Consent for Removal Actions (AOC) issued to Columbia Gas Transmission Corporation (Columbia) by the U.S. Environmental Protection Agency (EPA), Docket No. III-94-35-DC. An ASAR is submitted to support the removal of facilities from the Work Scope List (WSL) when information and data collected pursuant to the Active Screening Assessment Work Plan (ASAWP) for Gathering Line Liquid Removal Points (LRPs) demonstrate that no further investigation or cleanup is warranted under the AOC.

This ASAR includes the Facility Conditions Survey, Liquid Removal Point Questionnaire (if any), analytical sampling results, facility sketch(es) and facility photograph(s) for facility L05010 in accordance with the ASAWP. Please note that the facility sketch may show facilities other than L05010 due to their close proximity to each other. This report is only for facility L05010. The sample locations are shown on the sketches and are visible as colored pin flags on the photograph(s).

All analytical sampling results for L05010 are below ASA Action Levels, as shown in Table 2 and defined in the ASAWP. State Action Levels for this facility are presented in Table 3 as defined by the Ohio Environmental Protection Agency. The documentation presented in this report demonstrates that Columbia characterized and performed a response action at facility L05010 pursuant to the ASAWP and that no further investigation or cleanup is warranted under the AOC for this facility. Therefore, Columbia requests that facility L05010 be removed from the WSL pursuant to Section 8.5(d) of the AOC.

Facility ID:	L05010 Facility Description: D	ISPLACEMENT METER 732042 ON LINE Q-926
Facility Type:	LRP Latitude: 39° 22' 14.9" N	
Survey Date:	8/6/98 Longitude: 81° 40' 13.3" W	
A. GENERAL INFO	 Township/City: BARLOW TOWNSHIP County: Washington State: Ohio 	 5. District: SOUTHERN 6. Operating Location: ATHENS 7. Pipeline Number: Q-926
	4. Area: OHIO	8. Well Number: N/A
B. GENERAL FACILITY FEATURES	10. Soil Type of local exposures: 11. Description of predominant surrounding vegetation type: 12. Description of nearby surface water: Name: NONE VISIBLE FROM SITE Distance: % slope: Type: Subtype: Size: 13. Drainage pathways visible? NO 14. Are surrounding lands jurisdictional wetlands? NO 15. Accessibility of the site for characterization and remediation, if required to the surrounding lands in the surrounding lands? 16. Nearest utilities less than 1/4 mile? 17. Is cellular telephone service available? 18. Is overnight shipper nearby? (i.e. Federal Express)	ed: Road all the way to site YES, OVERHEAD LINES YES YES
	19. Are there any overhead obstructions that would affect remediation?	NO
C. ADJACENT LAND USE	 20. Surrounding land use: Agricultural 21. Approximate distance to nearby occupied structures (ft): 60 22. Evidence of public water services? NO 	Type of structure: HOUSE
D. EVIDENCE OF A RELEASE FROM AN LRP OR ASSOCIATED FEATURES	 23. Evidence of soil staining: NO 24. Surrounding vegetation stressed or discolored? NO 25. Evidence of release to nearby surface water? NO (e.g. oily sheen on top of surface water or along bank) 26. Has a release to the ground occurred at this facility? NO POSSIBLY IN THE PAST, BUT NOT TO GUIDE'S KNOWLEDGE 27. Approximate size of impacted area (sq ft): 	FE

	Facility ID: L05010
E. MMS	28. Type of Meter Station:
EVIDENCE OF A	29. Number of meters:
RELEASE	30. Describe the housing:
	31. Flooring:
	32. Number of doorways:
	33. Evidence of mercury on soil surface?
	34. Evidence of release in building?
	35. MVA reading inside doorway:
	36. Has a release to the ground occurred at this facility?
	37. Approximate size of impacted area (sq ft):
F. STORAGE	38. Evidence of soil staining?
WELL EVIDENCE	39. Surrounding vegetation stressed or discolored?
OF A	40. Evidence of release to nearby surface water?
RELEASE	41. Evidence of discharge at wellhead annulus?
	42. Nearby seeps with discharge and/or odor:
	43. Approximate size of impacted area (sq ft):

Employee Name: Aaron Gaskins	RFW Facility ID: L05010				
Date: 8/6/98 11:54:24	Columbia Facility Name, if any: 732042				
	Latitude: 39° 22' 14.9" N				
	Longitude: 81° 40' 13.3" W				
1. Removal point name: METER 732042 ON LINE Q-926	10. Pipeline number: Q-926				
2. Township/city: BARLOW TOWNSHIP	11. Associated well number: N/A				
3. County: Washington	12a. Associated metering station number: 732042				
4. State: Ohio	12b. Is this or was this a Mercury Metering Station?				
5. Area: OHIO	13a. Inventory station number: N/A				
	13b. Inventory map number: 4356-440				
6. District: SOUTHERN	14. Is the removal point on a backfed system? NO				
7. Operating location: ATHENS	15. How much liquid (gallons/year) has this removal point historically produced? $\bf 0$ - $\bf 10$				
8. Removal point type: Liquid Removal Point	16. If the removal point produced liquids, how often were the liquids collected historically? Once/Year				
9. Removal point function: TRANSMISSION	17. Approximately how many years has this removal point been in operation? 46				
	18. Approximately how many years have fluids been produced? 46				
	19. Is there knowledge of a release to the ground at this site? NO				
	This release is associated with:				
20a. How much liquid (gallons/year) has been released to the ground historical	ly? 0				
20b. Historical discharge characteristics:					
NONE					
21. If the removal point produced liquids, how often were these liquids releas	ed to the ground historically? Never				
22. If liquid releases have been identified in 19,20, or 21, what has been release	sed?				
23a. Has an historical, atypical release occurred at this site?					
23b. How much liquid (gallons) was released?					
23c. How many years ago was this release?					
24a. Are storage tanks associated with removal point? NO					
24b. Number of years since tank installation?					
25. Other surface or subsurface features associated with removal point:					

RFW Facility ID: L05010	
26. Evidence of soil staining:	NO
The staining is associated with:	
27. Evidence of stressed vegetation:	NO
The evidence is associated with:	
28. Approximate size of release are:	
29. Are there any nearby waterbodies:	NO
Approximate distance to waterbody:	
30. (Reserved for Site Sketch.)	
31. (Reserved for LRP Photograph.)	
32. Site Access Restrictions:	Road All The Way To Site
Distance from main road:	100 ft. to 1/4 Mile

Analytical Results Facility ID: L05010

			Analysis				Detection	
Field Sample ID	Matrix	Collected		Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05010-SS001-40001	S	8/6/98	GC BTEX(S)	BENZENE	ND		5.9	UG/KG
L05010-SS001-40001	S	8/6/98	GC BTEX(S)	ETHYL BENZENE	ND		5.9	UG/KG
L05010-SS001-40001	S	8/6/98	GC BTEX(S)	TOLUENE	ND		5.9	UG/KG
L05010-SS001-40001	S	8/6/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.9	UG/KG
L05010-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1016	ND		39	UG/KG
L05010-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1221	ND		39	UG/KG
L05010-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1232	ND		39	UG/KG
L05010-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1242	ND		39	UG/KG
L05010-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1248	ND		39	UG/KG
L05010-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1254	ND		39	UG/KG
L05010-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1260	ND		39	UG/KG
L05010-SS002-40001	S	8/6/98	GC BTEX(S)	BENZENE	ND		5.8	UG/KG
L05010-SS002-40001	S	8/6/98	GC BTEX(S)	ETHYL BENZENE	ND		5.8	UG/KG
L05010-SS002-40001	S	8/6/98	GC BTEX(S)	TOLUENE	ND		5.8	UG/KG
L05010-SS002-40001	S	8/6/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.8	UG/KG
L05010-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1016	ND		38	UG/KG
L05010-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1221	ND		38	UG/KG
L05010-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1232	ND		38	UG/KG
L05010-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1242	ND		38	UG/KG
L05010-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1248	ND		38	UG/KG
L05010-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1254	ND		38	UG/KG
L05010-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1260	ND		38	UG/KG

^{*} Legend:

J=Estimated Analytical Value UJ=Estimated Detection Limit J+ =Estimated Analytical Value, Possible Biased High J- =Estimated Analytical Value, Possibly Biased Low

R=Rejected Result




Facility ID: L05010 Photo Date:08/06/98 12:03 DISPLACEMENT METER 732042 ON LINE Q-926



Facility ID: L05010 Photo Date:08/06/98 12:04 DISPLACEMENT METER 732042 ON LINE Q-926

Facility ID: L05010 Sketch 1 of 1 SAMPLE DATE: 8/6/98 SKETCHED BY: A. Gaskins WESTON FACILITY ID: LOSO10 C COLUMBIA FACILITY ID/DESCRIPTION: Displacement Meter 732042 on Line 9-926 Washington 0 Co. Rd. 805 73 120' -> F Cattle Pasture > I Marker X) SSOOI SSOOD L05010 DISPLACEMENT METER @ Top of displacement meter to: SS001+1/1" SS002-7/8" To house ~ 60' From Line marker to: meter SS001-8/11" 55002-1011 x = measurement location SS001 (SAMPLE LOC.) REMINDERS YYYYY SLOPE Y I NORTH ARROW __ _ _ _ _ DIRT/GRAVEL RD SS001 ROAD NAMES OVERHEAD LINES ☐ ☆ GAS WELL PAVED ROAD SS002 M PHOTO DIRECTION - -- UNDRGD PIPELINE Y Х LINE MARKERS EXPOSED PIPELINE OCCUPIED STRUCTURES ☑ Ø GPS LOCATION SS001 =::=:= streamcreek BUILDINGS APPROX. SCALE: 1 block SS002 I SURFACE WATERS → DIRECTION OF FLOW



SUMMARY OF FINDINGS AND RECOMMENDATIONS

This report has been prepared as part of the Active Screening Assessment (ASA), as defined under the Administrative Order on Consent for Removal Actions (AOC) issued to Columbia Gas Transmission Corporation (Columbia) by the U.S. Environmental Protection Agency (EPA), Docket No. III-94-35-DC. An ASAR is submitted to support the removal of facilities from the Work Scope List (WSL) when information and data collected pursuant to the Active Screening Assessment Work Plan (ASAWP) for Gathering Line Liquid Removal Points (LRPs) demonstrate that no further investigation or cleanup is warranted under the AOC.

This ASAR includes the Facility Conditions Survey, Liquid Removal Point Questionnaire (if any), analytical sampling results, facility sketch(es) and facility photograph(s) for facility L05011 in accordance with the ASAWP. Please note that the facility sketch may show facilities other than L05011 due to their close proximity to each other. This report is only for facility L05011. The sample locations are shown on the sketches and are visible as colored pin flags on the photograph(s).

All analytical sampling results for L05011 are below ASA Action Levels, as shown in Table 2 and defined in the ASAWP. State Action Levels for this facility are presented in Table 3 as defined by the Ohio Environmental Protection Agency. The documentation presented in this report demonstrates that Columbia characterized and performed a response action at facility L05011 pursuant to the ASAWP and that no further investigation or cleanup is warranted under the AOC for this facility. Therefore, Columbia requests that facility L05011 be removed from the WSL pursuant to Section 8.5(d) of the AOC.

Facility ID:		DISPLACEMENT METER 722705 ON LINE Q-926EAGLE MTN							
Facility Type:	LRP Latitude: 39° 21' 29.0" N	DDY							
Survey Date:	8/6/98 Longitude: 81° 40' 25.5" W								
A. GENERAL	1. Township/City: BARLOW TOWNSHIP	5. District: SOUTHERN							
INFO	2. County: Washington	6. Operating Location: ATHENS							
	3. State: Ohio	7. Pipeline Number: Q-926							
	4. Area: OHIO	8. Well Number: N/A							
B. GENERAL	9. Description of Facility Topography: Sloping	(8 - 15 % slope)							
FACILITY FEATURES	10. Soil Type of local exposures: Sandy L	oam							
	11. Description of predominant surrounding vegetation type: Lawn (N	faintained)							
	12. Description of nearby surface water: Name: NONE VISIBLE FROM SITE								
	Distance: % slope:								
	% stope: Type:								
	Subtype: Size:								
	13. Drainage pathways visible? NO								
	14. Are surrounding lands jurisdictional wetlands? NO								
	15. Accessibility of the site for characterization and remediation, if required: Road all the way to site								
	16. Nearest utilities less than 1/4 mile?	YES, OVERHEAD LINES							
	17. Is cellular telephone service available?	YES							
	18. Is overnight shipper nearby? (i.e. Federal Express)	YES							
	19. Are there any overhead obstructions that would affect remediation?	NO							
C. ADJACENT	20. Surrounding land use: Residential								
LAND USE	21. Approximate distance to nearby occupied structures (ft): 600	Type of structure: HOUSE							
	22. Evidence of public water services? NO								
D. EVIDENCE	23. Evidence of soil staining: NO								
OF A RELEASE	24. Surrounding vegetation stressed or discolored? NO								
FROM AN	25. Evidence of release to nearby surface water? NO								
LRP OR ASSOCIATED	(e.g. oily sheen on top of surface water or along bank)								
FEATURES	26. Has a release to the ground occurred at this facility? NO POSSIBLY IN THE PAST, BUT NOT TO GUIDE'S KNOWLEDG	GE							
	27. Approximate size of impacted area (sq ft):								

	Facility ID: L05011
E. MMS EVIDENCE OF A RELEASE	28. Type of Meter Station: 29. Number of meters: 30. Describe the housing: 31. Flooring: 32. Number of doorways: 33. Evidence of mercury on soil surface? 34. Evidence of release in building? 35. MVA reading inside doorway: 36. Has a release to the ground occurred at this facility? 37. Approximate size of impacted area (sq ft):
F. STORAGE WELL EVIDENCE OF A RELEASE	 38. Evidence of soil staining? 39. Surrounding vegetation stressed or discolored? 40. Evidence of release to nearby surface water? 41. Evidence of discharge at wellhead annulus? 42. Nearby seeps with discharge and/or odor: 43. Approximate size of impacted area (sq ft):

Employee Name: Aaron Gaskins	RFW Facility ID: L05011
Date: 8/6/98 13:35:42	Columbia Facility Name, if any: 722705
	Latitude: 39° 21' 29.0" N
	Longitude: 81° 40' 25.5" W
1. Removal point name: METER 722705 ON LINE Q-926	10. Pipeline number: Q-926
2. Township/city: BARLOW TOWNSHIP	11. Associated well number: N/A
3. County: Washington	12a. Associated metering station number: 722705
4. State: Ohio	12b. Is this or was this a Mercury Metering Station?
5. Area: OHIO	13a. Inventory station number: N/A
	13b. Inventory map number: 4356-440
6. District: SOUTHERN	14. Is the removal point on a backfed system? NO
7. Operating location: ATHENS	15. How much liquid (gallons/year) has this removal point historically produced? 0 - 10
8. Removal point type: Liquid Removal Point	16. If the removal point produced liquids, how often were the liquids collected historically? Once/Year
9. Removal point function: TRANSMISSION	17. Approximately how many years has this removal point been in operation? >20
	18. Approximately how many years have fluids been produced? >20
	19. Is there knowledge of a release to the ground at this site?
	This release is associated with:
20a. How much liquid (gallons/year) has been released to the ground historical	lly? 0
20b. Historical discharge characteristics:	
NONE	
21. If the removal point produced liquids, how often were these liquids releas	ed to the ground historically? Never
22. If liquid releases have been identified in 19,20, or 21, what has been release	sed?
23a. Has an historical, atypical release occurred at this site?	
23b. How much liquid (gallons) was released?	
23c. How many years ago was this release?	
24a. Are storage tanks associated with removal point? NO	
24b. Number of years since tank installation?	
25. Other surface or subsurface features associated with removal point:	

RFW Facility ID: L05011		
26. Evidence of soil staining:	NO	
The staining is associated with:		
27. Evidence of stressed vegetation:	NO	
The evidence is associated with:		
28. Approximate size of release are		
29. Are there any nearby waterbodies:	NO	
Approximate distance to waterbody:		
30. (Reserved for Site Sketch.)		
31. (Reserved for LRP Photograph.)		
32. Site Access Restrictions:	Road All The Way To Site	
Distance from main road:	100 ft. to 1/4 Mile	

Analytical Results Facility ID: L05011

			Analysis				Detection	
Field Sample ID	Matrix	Collected	Category	Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05011-SS001-40001	S	8/6/98	GC BTEX(S)	BENZENE	ND		6.0	UG/KG
L05011-SS001-40001	S	8/6/98	GC BTEX(S)	ETHYL BENZENE	ND		6.0	UG/KG
L05011-SS001-40001	S	8/6/98	GC BTEX(S)	TOLUENE	ND		6.0	UG/KG
L05011-SS001-40001	S	8/6/98	GC BTEX(S)	XYLENES (TOTAL)	ND		6.0	UG/KG
L05011-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1016	ND		39	UG/KG
L05011-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1221	ND		39	UG/KG
L05011-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1232	ND		39	UG/KG
L05011-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1242	ND		39	UG/KG
L05011-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1248	ND		39	UG/KG
L05011-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1254	ND		39	UG/KG
L05011-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1260	ND		39	UG/KG
L05011-SS002-40001	S	8/6/98	GC BTEX(S)	BENZENE	ND		5.9	UG/KG
L05011-SS002-40001	S	8/6/98	GC BTEX(S)	ETHYL BENZENE	ND		5.9	UG/KG
L05011-SS002-40001	S	8/6/98	GC BTEX(S)	TOLUENE	ND		5.9	UG/KG
L05011-SS002-40001	S	8/6/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.9	UG/KG
L05011-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1016	ND		39	UG/KG
L05011-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1221	ND		39	UG/KG
L05011-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1232	ND		39	UG/KG
L05011-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1242	ND		39	UG/KG
L05011-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1248	ND		39	UG/KG
L05011-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1254	ND		39	UG/KG
L05011-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1260	ND		39	UG/KG

^{*} Legend:

J=Estimated Analytical Value UJ=Estimated Detection Limit J+ =Estimated Analytical Value, Possible Biased High J- =Estimated Analytical Value, Possibly Biased Low

R=Rejected Result



Facility ID: L05011 Photo Date:08/06/98 13:58 DISPLACEMENT METER 722705 ON LINE Q-926



Facility ID: L05011 Photo Date:08/06/98 13:58 DISPLACEMENT METER 722705 ON LINE Q-926

Facility ID: L05011 Sketch 1 of 1_ NESTON FACILITY ID: LOSOII SAMPLE DATE: 8/6/98 SKETCHED BY: A. GOSKINS \subset COLUMBIA FACILITY IDIDESCRIPTION: Displacement Meter 722705 on Line Q-926 Ø I 1-Œ \$S002 0 LOSOH METER Z S5001 OLine Marker @ Hilly, grassy, Top of displacement meter to: 55001-16" To Washington SS 002 - 7'9" End of pipe to ! To house 55001-2'4" ~600' 55002-51" 4 X = measurement

No cation

SS001 (SAMPLE LOC.) **REMINDERS** YYYYY SLOPE Y Х 1 NORTH ARROW ====== DIRT/GRAVEL RD SS001 1 ROAD NAMES ☐ ☆ GAS WELL __ PAVED ROAD SS002] OVERHEAD LINES M PHOTO DIRECTION UNDRGD PIPELINE Х Y LINE MARKERS ---- EXPOSED PIPELINE 1 OCCUPIED STRUCTURES **☑** ⊗ GPS LOCATION SS001) BUILDINGS SS002 APPROX. SCALE: I block SURFACE WATERS DIRECTION OF FLOW

L05012

HORIZONTAL DRIP ON LINE Q-926 AT STATION 617+39

SUMMARY OF FINDINGS AND RECOMMENDATIONS

This report has been prepared as part of the Active Screening Assessment (ASA), as defined under the Administrative Order on Consent for Removal Actions (AOC) issued to Columbia Gas Transmission Corporation (Columbia) by the U.S. Environmental Protection Agency (EPA), Docket No. III-94-35-DC. An ASAR is submitted to support the removal of facilities from the Work Scope List (WSL) when information and data collected pursuant to the Active Screening Assessment Work Plan (ASAWP) for Gathering Line Liquid Removal Points (LRPs) demonstrate that no further investigation or cleanup is warranted under the AOC.

This ASAR includes the Facility Conditions Survey, Liquid Removal Point Questionnaire (if any), analytical sampling results, facility sketch(es) and facility photograph(s) for facility L05012 in accordance with the ASAWP. Please note that the facility sketch may show facilities other than L05012 due to their close proximity to each other. This report is only for facility L05012. The sample locations are shown on the sketches and are visible as colored pin flags on the photograph(s).

All analytical sampling results for L05012 are below ASA Action Levels, as shown in Table 2 and defined in the ASAWP. State Action Levels for this facility are presented in Table 3 as defined by the Ohio Environmental Protection Agency. The documentation presented in this report demonstrates that Columbia characterized and performed a response action at facility L05012 pursuant to the ASAWP and that no further investigation or cleanup is warranted under the AOC for this facility. Therefore, Columbia requests that facility L05012 be removed from the WSL pursuant to Section 8.5(d) of the AOC.

Facility ID:	L05012 Facility Description:	HORIZONTAL DRIP ON LINE Q-926 AT STATION 617+39						
Facility Type:	LRP Latitude: 39° 14' 26.5" N							
Survey Date:	8/6/98 Longitude: 81° 42' 48.0" W							
A. GENERAL	1. Township/City: BELPRE TOWNSHIP	5. District: SOUTHERN						
INFO	2. County: Washington	6. Operating Location: ATHENS						
	3. State: Ohio	7. Pipeline Number: Q-926						
	4. Area: OHIO	8. Well Number: N/A						
B. GENERAL	9. Description of Facility Topography: Sloping	(8 - 15 % slope)						
FACILITY FEATURES	10. Soil Type of local exposures: Clay Lo	am						
1 Li II ORLIS	11. Description of predominant surrounding vegetation type: Forest							
	12. Description of nearby surface water: Name: NONE VISIBLE FROM SITE Distance: % slope: Type: Subtype: Size:							
	13. Drainage pathways visible? NO							
	14. Are surrounding lands jurisdictional wetlands? NO							
	15. Accessibility of the site for characterization and remediation, if required: No Road							
	16. Nearest utilities less than 1/4 mile?	NO						
	17. Is cellular telephone service available?	YES						
	18. Is overnight shipper nearby? (i.e. Federal Express)	YES						
	19. Are there any overhead obstructions that would affect remediation?	YES, TREES						
C. ADJACENT	20. Surrounding land use: Residential							
LAND USE	21. Approximate distance to nearby occupied structures (ft): 50	Type of structure: HOUSE						
	22. Evidence of public water services? NO							
D. EVIDENCE	23. Evidence of soil staining: NO							
OF A RELEASE	24. Surrounding vegetation stressed or discolored? NO							
FROM AN LRP OR	25. Evidence of release to nearby surface water? NO (e.g. oily sheen on top of surface water or along bank)							
ASSOCIATED FEATURES	26. Has a release to the ground occurred at this facility? NO POSSIBLY IN THE PAST, BUT NOT TO GUIDE'S KNOWLEDGE							
	27. Approximate size of impacted area (sq ft):							

	Facility ID: L05012
E. MMS	28. Type of Meter Station:
EVIDENCE OF A	29. Number of meters:
RELEASE	30. Describe the housing:
	31. Flooring:
	32. Number of doorways:
	33. Evidence of mercury on soil surface?
	34. Evidence of release in building?
	35. MVA reading inside doorway:
	36. Has a release to the ground occurred at this facility?
	37. Approximate size of impacted area (sq ft):
F. STORAGE	38. Evidence of soil staining?
WELL EVIDENCE	39. Surrounding vegetation stressed or discolored?
OF A	40. Evidence of release to nearby surface water?
RELEASE	41. Evidence of discharge at wellhead annulus?
	42. Nearby seeps with discharge and/or odor:
	43. Approximate size of impacted area (sq ft):

Employee Name: Aaron Gaskins	RFW Facility ID: L05012
Date: 8/6/98 15:15:36	Columbia Facility Name, if any:
	Latitude: 39° 14' 26.5" N
	Longitude: 81° 42' 48.0" W
1. Removal point name: DRIP ON LINE Q-926	10. Pipeline number: Q-926
2. Township/city: BELPRE TOWNSHIP	11. Associated well number: N/A
3. County: Washington	12a. Associated metering station number: N/A
4. State: Ohio	12b. Is this or was this a Mercury Metering Station?
5. Area: OHIO	13a. Inventory station number: 617+39
	13b. Inventory map number: 4340+436
6. District: SOUTHERN	14. Is the removal point on a backfed system? NO
7. Operating location: ATHENS	15. How much liquid (gallons/year) has this removal point historically produced? 0 - 10
8. Removal point type: Liquid Removal Point	16. If the removal point produced liquids, how often were the liquids collected historically? Once/Year
9. Removal point function: TRANSMISSION	17. Approximately how many years has this removal point been in operation? >40
	18. Approximately how many years have fluids been produced? >40
	19. Is there knowledge of a release to the ground at this site?
	This release is associated with:
20a. How much liquid (gallons/year) has been released to the ground historica	lly? 0
20b. Historical discharge characteristics:	
NONE	
21. If the removal point produced liquids, how often were these liquids releas	ed to the ground historically? Never
22. If liquid releases have been identified in 19,20, or 21, what has been release	sed?
23a. Has an historical, atypical release occurred at this site?	
23b. How much liquid (gallons) was released?	
23c. How many years ago was this release?	
24a. Are storage tanks associated with removal point? NO	
24b. Number of years since tank installation?	
25. Other surface or subsurface features associated with removal point:	

RFW Facility ID: L05012	
26. Evidence of soil staining:	NO
The staining is associated with:	
27. Evidence of stressed vegetation:	NO
The evidence is associated with:	
28. Approximate size of release are:	
29. Are there any nearby waterbodies:	: NO
Approximate distance to waterbody:	:
30. (Reserved for Site Sketch.)	
31. (Reserved for LRP Photograph.)	
32. Site Access Restrictions:	No Road
Distance from main road:	100 ft. to 1/4 Mile

Analytical Results Facility ID: L05012

			Analysis				Detection		
Field Sample ID	Matrix	Collected	Category	Parameter	Result	Flag*	Limit	Units	
Characterization Samples									
L05012-SS001-40001	S	8/6/98	GC BTEX(S)	BENZENE	ND		7.1	UG/KG	
L05012-SS001-40001	S	8/6/98	GC BTEX(S)	ETHYL BENZENE	28		7.1	UG/KG	
L05012-SS001-40001	S	8/6/98	GC BTEX(S)	TOLUENE	ND		7.1	UG/KG	
L05012-SS001-40001	S	8/6/98	GC BTEX(S)	XYLENES (TOTAL)	ND		7.1	UG/KG	
L05012-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1016	ND		47	UG/KG	
L05012-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1221	ND		47	UG/KG	
L05012-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1232	ND		47	UG/KG	
L05012-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1242	ND		47	UG/KG	
L05012-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1248	ND		47	UG/KG	
L05012-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1254	ND		47	UG/KG	
L05012-SS001-40001	S	8/6/98	PCB(S)	AROCLOR-1260	ND		47	UG/KG	
L05012-SS002-40001	S	8/6/98	GC BTEX(S)	BENZENE	ND		7.5	UG/KG	
L05012-SS002-40001	S	8/6/98	GC BTEX(S)	ETHYL BENZENE	ND		7.5	UG/KG	
L05012-SS002-40001	S	8/6/98	GC BTEX(S)	TOLUENE	ND		7.5	UG/KG	
L05012-SS002-40001	S	8/6/98	GC BTEX(S)	XYLENES (TOTAL)	ND		7.5	UG/KG	
L05012-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1016	ND		49	UG/KG	
L05012-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1221	ND		49	UG/KG	
L05012-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1232	ND		49	UG/KG	
L05012-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1242	ND		49	UG/KG	
L05012-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1248	ND		49	UG/KG	
L05012-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1254	ND		49	UG/KG	
L05012-SS002-40001	S	8/6/98	PCB(S)	AROCLOR-1260	ND		49	UG/KG	

^{*} Legend:

J=Estimated Analytical Value UJ=Estimated Detection Limit J+ =Estimated Analytical Value, Possible Biased High J- =Estimated Analytical Value, Possibly Biased Low

R=Rejected Result



Facility ID: L05012 Photo Date:08/06/98 15:20 HORIZONTAL DRIP ON LINE Q-926 AT STATION 617+39



Facility ID: L05012 Photo Date:08/06/98 15:21 HORIZONTAL DRIP ON LINE Q-926 AT STATION 617+39

L05013

SIPHON ON LINE H-118 AT STATION 243+28

SUMMARY OF FINDINGS AND RECOMMENDATIONS

This report has been prepared as part of the Active Screening Assessment (ASA), as defined under the Administrative Order on Consent for Removal Actions (AOC) issued to Columbia Gas Transmission Corporation (Columbia) by the U.S. Environmental Protection Agency (EPA), Docket No. III-94-35-DC. An ASAR is submitted to support the removal of facilities from the Work Scope List (WSL) when information and data collected pursuant to the Active Screening Assessment Work Plan (ASAWP) for Gathering Line Liquid Removal Points (LRPs) demonstrate that no further investigation or cleanup is warranted under the AOC.

This ASAR includes the Facility Conditions Survey, Liquid Removal Point Questionnaire (if any), analytical sampling results, facility sketch(es) and facility photograph(s) for facility L05013 in accordance with the ASAWP. Please note that the facility sketch may show facilities other than L05013 due to their close proximity to each other. This report is only for facility L05013. The sample locations are shown on the sketches and are visible as colored pin flags on the photograph(s).

All analytical sampling results for L05013 are below ASA Action Levels, as shown in Table 2 and defined in the ASAWP. State Action Levels for this facility are presented in Table 3 as defined by the Ohio Environmental Protection Agency. The documentation presented in this report demonstrates that Columbia characterized and performed a response action at facility L05013 pursuant to the ASAWP and that no further investigation or cleanup is warranted under the AOC for this facility. Therefore, Columbia requests that facility L05013 be removed from the WSL pursuant to Section 8.5(d) of the AOC.

Facility ID:	L05013 Facility Description: SI	PHON ON LINE H-118 AT STATION 243+28
Facility Type:	LRP Latitude:	
Survey Date:	8/7/98 Longitude:	
A. GENERAL INFO	 Township/City: MONROE TWSP County: Perry State: Ohio Area: OHIO 	5. District: SOUTHERN 6. Operating Location: ATHENS 7. Pipeline Number: H-118 8. Well Number: N/A
B. GENERAL FACILITY FEATURES	9. Description of Facility Topography: 10. Soil Type of local exposures: 11. Description of predominant surrounding vegetation type: 12. Description of nearby surface water: Name: NONE VISIBLE FROM SITE Distance: % slope: Type: Subtype: Size: 13. Drainage pathways visible? NO 14. Are surrounding lands jurisdictional wetlands? NO 15. Accessibility of the site for characterization and remediation, if required to the content of the content	
C. ADJACENT LAND USE	 20. Surrounding land use: Undeveloped 21. Approximate distance to nearby occupied structures (ft): 22. Evidence of public water services? NO 	Type of structure: NONE VISIBLE FROM SITE
D. EVIDENCE OF A RELEASE FROM AN LRP OR ASSOCIATED FEATURES	 23. Evidence of soil staining: NO 24. Surrounding vegetation stressed or discolored? NO 25. Evidence of release to nearby surface water? NO (e.g. oily sheen on top of surface water or along bank) 26. Has a release to the ground occurred at this facility? NO POSSIBLY IN THE PAST, BUT NOT TO GUIDE'S KNOWLEDG 27. Approximate size of impacted area (sq ft): 	JE

	Facility ID: L05013				
E. MMS EVIDENCE OF A RELEASE	28. Type of Meter Station:				
	29. Number of meters:				
	Describe the housing: Flooring:				
	32. Number of doorways:				
	33. Evidence of mercury on soil surface?				
	34. Evidence of release in building?				
	35. MVA reading inside doorway:				
	36. Has a release to the ground occurred at this facility?				
	37. Approximate size of impacted area (sq ft):				
F. STORAGE WELL EVIDENCE	38. Evidence of soil staining?				
	39. Surrounding vegetation stressed or discolored?				
OF A	40. Evidence of release to nearby surface water?				
RELEASE	41. Evidence of discharge at wellhead annulus?				
	42. Nearby seeps with discharge and/or odor:				
	43. Approximate size of impacted area (sq ft):				

Employee Name: Josh Mannke	RFW Facility ID: L05013				
Date: 8/7/98 10:12:15	Columbia Facility Name, if any:				
	Latitude:				
	Longitude:				
1. Removal point name: SIPHON ON LINE H-118	10. Pipeline number: H-118				
2. Township/city: MONROE TWSP	11. Associated well number: N/A				
3. County: Perry	12a. Associated metering station number: N/A				
4. State: Ohio	12b. Is this or was this a Mercury Metering Station?				
5. Area: OHIO	13a. Inventory station number: 243+28				
	13b. Inventory map number: 4384-408				
6. District: SOUTHERN	14. Is the removal point on a backfed system? NO				
7. Operating location: ATHENS	15. How much liquid (gallons/year) has this removal point historically produced? 0 - 10				
8. Removal point type: Liquid Removal Point	16. If the removal point produced liquids, how often were the liquids collected historically? Once/Year				
9. Removal point function: TRANSMISSION	17. Approximately how many years has this removal point been in operation? >20				
	18. Approximately how many years have fluids been produced? >20				
	19. Is there knowledge of a release to the ground at this site?				
	This release is associated with:				
20a. How much liquid (gallons/year) has been released to the ground historical	ly? 0				
20b. Historical discharge characteristics:					
NONE					
21. If the removal point produced liquids, how often were these liquids releas	ed to the ground historically? Never				
22. If liquid releases have been identified in 19,20, or 21, what has been release	sed?				
23a. Has an historical, atypical release occurred at this site?					
23b. How much liquid (gallons) was released?					
23c. How many years ago was this release?					
24a. Are storage tanks associated with removal point? NO					
24b. Number of years since tank installation?					
25. Other surface or subsurface features associated with removal point:					

RFW Facility ID: L05013	
26. Evidence of soil staining:	NO
The staining is associated with:	
27. Evidence of stressed vegetation:	NO
The evidence is associated with:	
28. Approximate size of release are	
29. Are there any nearby waterbodies:	: NO
Approximate distance to waterbody:	:
30. (Reserved for Site Sketch.)	
31. (Reserved for LRP Photograph.)	
32. Site Access Restrictions:	No Road
Distance from main road:	Greater Than 1/4 Mile

Analytical Results Facility ID: L05013

			Analysis			Detection			
Field Sample ID	Matrix	Collected		Parameter	Result	Flag*	Limit	Units	
Characterization Samples									
L05013-SS001-40001	S	8/7/98	GC BTEX(S)	BENZENE	ND		5.9	UG/KG	
L05013-SS001-40001	S	8/7/98	GC BTEX(S)	ETHYL BENZENE	ND		5.9	UG/KG	
L05013-SS001-40001	S	8/7/98	GC BTEX(S)	TOLUENE	ND		5.9	UG/KG	
L05013-SS001-40001	S	8/7/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.9	UG/KG	
L05013-SS001-40001	S	8/7/98	PCB(S)	AROCLOR-1016	ND		39	UG/KG	
L05013-SS001-40001	S	8/7/98	PCB(S)	AROCLOR-1221	ND		39	UG/KG	
L05013-SS001-40001	S	8/7/98	PCB(S)	AROCLOR-1232	ND		39	UG/KG	
L05013-SS001-40001	S	8/7/98	PCB(S)	AROCLOR-1242	ND		39	UG/KG	
L05013-SS001-40001	S	8/7/98	PCB(S)	AROCLOR-1248	ND		39	UG/KG	
L05013-SS001-40001	S	8/7/98	PCB(S)	AROCLOR-1254	ND		39	UG/KG	
L05013-SS001-40001	S	8/7/98	PCB(S)	AROCLOR-1260	ND		39	UG/KG	
L05013-SS001-41001 (Field Dup)	S	8/7/98	GC BTEX(S)	BENZENE	ND		5.9	UG/KG	
L05013-SS001-41001 (Field Dup)	S	8/7/98	GC BTEX(S)	ETHYL BENZENE	ND		5.9	UG/KG	
L05013-SS001-41001 (Field Dup)	S	8/7/98	GC BTEX(S)	TOLUENE	ND		5.9	UG/KG	
L05013-SS001-41001 (Field Dup)	S	8/7/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.9	UG/KG	
L05013-SS001-41001 (Field Dup)	S	8/7/98	PCB(S)	AROCLOR-1016	ND		39	UG/KG	
L05013-SS001-41001 (Field Dup)	S	8/7/98	PCB(S)	AROCLOR-1221	ND		39	UG/KG	
L05013-SS001-41001 (Field Dup)	S	8/7/98	PCB(S)	AROCLOR-1232	ND		39	UG/KG	
L05013-SS001-41001 (Field Dup)	S	8/7/98	PCB(S)	AROCLOR-1242	ND		39	UG/KG	
L05013-SS001-41001 (Field Dup)	S	8/7/98	PCB(S)	AROCLOR-1248	ND		39	UG/KG	
L05013-SS001-41001 (Field Dup)	S	8/7/98	PCB(S)	AROCLOR-1254	ND		39	UG/KG	
L05013-SS001-41001 (Field Dup)	S	8/7/98	PCB(S)	AROCLOR-1260	ND		39	UG/KG	

Analytical Results Facility ID: L05013

			Analysis				Detection	
Field Sample ID	Matrix	Collected	Category	Parameter	Result	Flag*	Limit	Units
Characterization Samples								
L05013-SS002-40001	S	8/7/98	GC BTEX(S)	BENZENE	ND		5.5	UG/KG
L05013-SS002-40001	S	8/7/98	GC BTEX(S)	ETHYL BENZENE	ND		5.5	UG/KG
L05013-SS002-40001	S	8/7/98	GC BTEX(S)	TOLUENE	ND		5.5	UG/KG
L05013-SS002-40001	S	8/7/98	GC BTEX(S)	XYLENES (TOTAL)	ND		5.5	UG/KG
L05013-SS002-40001	S	8/7/98	PCB(S)	AROCLOR-1016	ND		36	UG/KG
L05013-SS002-40001	S	8/7/98	PCB(S)	AROCLOR-1221	ND		36	UG/KG
L05013-SS002-40001	S	8/7/98	PCB(S)	AROCLOR-1232	ND		36	UG/KG
L05013-SS002-40001	S	8/7/98	PCB(S)	AROCLOR-1242	ND		36	UG/KG
L05013-SS002-40001	S	8/7/98	PCB(S)	AROCLOR-1248	ND		36	UG/KG
L05013-SS002-40001	S	8/7/98	PCB(S)	AROCLOR-1254	ND		36	UG/KG
L05013-SS002-40001	S	8/7/98	PCB(S)	AROCLOR-1260	ND		36	UG/KG

^{*} Legend:

J=Estimated Analytical Value UJ=Estimated Detection Limit J+ =Estimated Analytical Value, Possible Biased High J- =Estimated Analytical Value, Possibly Biased Low

R=Rejected Result



Facility ID: L05013 Photo Date:08/07/98 10:03 SIPHON ON LINE H-118 AT STATION 243+28



Facility ID: L05013 Photo Date:08/07/98 10:03 SIPHON ON LINE H-118 AT STATION 243+28

Facility ID: L05013 Sketch 1 of 1

